





General information

Make	MERCEDES
Model	ML ML 280 CDI EDITION S
Colour	Black
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 2.800 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.8 mpg
CO2 emission	254 g/km
CO2 label	L







Internet history

Entry	1
Date	

Pictures

2021-09-26

12

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-07
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	10
Total items failed	17

MOT #19	2023-12-07 10:58
MOT test number	786316256626
Result	✓ Passed
Next expiry date	2024-12-07

MOT #1	L8	2023-12-06 12:58
MOT te	st number	150098560431
Result		🗙 Failed
Fail	Offside Front Service brake excessively binding (1.2.1 (f))	
Fail	Offside Front Brake disc contaminated heat damage (1.1.14 (b))	
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail	Offside Front Brake pad(s) contaminated heat damage (1.1.13 (b))	

MOT #17	2022-12-07 11:15
MOT test number	869616129356
Result	✓ Passed

MOT #16	2021-12-08 11:52
MOT test number	960531032098
Result	✓ Passed





MOT #15	2020-12-03 10:34
MOT test number	548049116860
Result	✓ Passed
MOT #14	2019-12-05 13:22
MOT test number	867248499676
Result	✓ Passed
MOT #13	2018-12-21 13:17
MOT test number	254841897776
Result	✓ Passed
MOT #12	2018-01-12 13:25
MOT test number	985275656274
Result	✓ Passed
MOT #11	2017-01-21 08:24
MOT test number	761246080260
Result	✓ Passed
Advice Offside Front Obligatory mirror damaged, but not seriously affecting the rear	view (8.1.2a)
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #10	2015-08-05 15:13
MOT test number	847837115251
Result	✓ Passed





МОТ #9		2015-08-05 15:13
MOT test number		328857515475
Result		🗙 Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)	
Pass with rectification	Nearside Headlamp aim too high (1.8)	
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)	

МОТ #8	2015-07-22 13:00
MOT test number	349153205491
Result	🗙 Failed
Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)	
Fail Nearside Front Side repeater not working (1.4.A.2c)	
Fail Nearside Headlamp not working on main beam (1.7.5a)	
MOT #7	2014-07-11 15:25
NOT to at your bar	227222004140

MOT test	number	327322894149
Result		✓ Passed
Notice	Brake pedal anti slip worn	
Notice	Offside front tyre cut in outer side wall	





MOT #6	2014-07-10 13:36
MOT test number	649731394101
Result	🗙 Failed
Fail Offside Headlamp not working on dipped beam (1.7.5a)	
Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structur	re (4.1.D.1b)
Notice Brake pedal anti slip worn	
Fail Offside Stop lamp not working (1.2.1b)	
FailOffside Side repeater not working (1.4.A.2c)	
Notice Offside front tyre cut in outer side wall	

MOT #5	2013-07-29 12:06
MOT test number	186090013262
Result	✓ Passed

МОТ #4	2013-07-25 18:13
MOT test number	478386803272
Result	🗙 Failed
Fail Nearside Headlamp not working on dipped beam (1.7.5a)	
Fail Offside Stop lamp not working (1.2.1b)	
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to (4.1.D.1a)	reach the ply or cords

MOT #3	2012-07-27 17:09
MOT test number	609109402230
Result	✓ Passed





MOT #2		2011-07-22 14:47
MOT test	number	719813301283
Result		✓ Passed
Notice	Nail in nearside front tyre	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Nail in offside rear tyre	
MOT #1		2010-06-28 16:39
MOT test	number	151789970122
Result		✓ Passed



Tax & MOT check

✓ Taxed	√ МОТ	
Tax due: 1 March 2025	Expires: 7 December 2024	
Tax status	Valid until 1 March	
Days left	306	
MOT expiry date	7 December 2024	
Full MOT history	See MOT history	

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	VAMPLE
Date	
Category	AMP
Туре	

Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
See in this check in this MERCEDES had uncreate humber plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Carrent registration	
Carrent registration Plate since	





Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-19
Last registration	2023-12-07
Complete history	See info



Registration #1	2007-09-19	9 mi
Registration #2	2010-06-28	26.762 mi
Registration #3	2011-07-22	29.605 mi
Registration #4	2012-07-27	31.886 mi
Registration #5	2013-07-25	35.243 mi
Registration #6	2013-07-29	35.258 mi
Registration #7	2014-07-10	37.999 mi
Registration #8	2014-07-11	38.001 mi
Registration #9	2015-07-22	39.897 mi
Registration #10	2015-08-05	39.913 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 mi
Registration #19		11.777 mi
Registration #20		11.117 mi





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1911 mm
Height	1884 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg
Additional information	
Fuel tank capacity	95 l
	95 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5