





report date: 2024-03-28

## General information

| Make                | HYUNDAI           |
|---------------------|-------------------|
| Model               | IONIQ PREMIUM S   |
| Colour              | Silver            |
| Year of manufacture | 2018              |
| Top speed           | 115 mph           |
| 0 - 60 mph          | 11.1 seconds      |
| Gearbox             | 6 speed automatic |

## Engine & fuel consumption

| Power                   | 140 BHP             |
|-------------------------|---------------------|
| Max. torque             | 265 Nm at 4.000 rpm |
| Engine capacity         | 1.580 cc            |
| Cylinders               | 4                   |
| Fuel type               | Hybrid / Electric   |
| Consumption city        | 72.7 mpg            |
| Consumption extra urban | 71.9 mpg            |
| Consumption combined    | 72.4 mpg            |
| CO2 emission            | 79 g/km             |
| CO2 label               | А                   |



CarCheck.co.uk page 1/10



report date: 2024-03-28

### Internet history

### Entry 2

Date 2021-07-12

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

| Date | 2021-06-30 |
|------|------------|
|      |            |

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

✓ Passed

# MOT history

Result

| MOT expiry date    | 2024-06-29 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 3          |
| Failed MOT tests   | 0          |
| Total advice items | 3          |
| Total items failed | 0          |

| MOT #3   |        | 2023-06-28 08:21 |
|--|--------|------------------|
| MOT test   | number | 135418772860     |
| Result   |        | <b>✓</b> Passed  |
| Next expiry date 2024-06-29  |        |                  |
| Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |        |                  |
| Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))                    |        |                  |
| Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))  |        |                  |

| MOT #2          | 2022-06-16 11:23 |
|-----------------|------------------|
| MOT test number | 825445011204     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #1          | 2021-06-30 14:37 |
| MOT test number | 193390368145     |

CarCheck.co.uk page 3/10



**CSZ1375**report date: 2024-03-28

Tax & MOT check



| Tax status       | Valid until 1 July |
|------------------|--------------------|
| Days left        | 63                 |
| MOT expiry date  | 29 June 2024       |
| Full MOT history | See MOT history    |

### Tax calculation

| Vehicle class                 | 59         |
|-------------------------------|------------|
| Band                          | D          |
| First licence fee (12 months) | £ 120,00,- |
| Standard rate (12 months)     | £ 170,00,- |
| Standard rate (6 months)      | £ 93,50,-  |
| Premium rate (12 months)      | £ 560,00,- |
| Premium rate (6 months)       | £ 308,00,- |

CarCheck.co.uk page 4/10



**CSZ1375**report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



**CSZ1375**report date: 2024-03-28

Owner history

| e when miscory  |               |      |
|---|---------------|------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is |               | NDAI |
| **************************************  |               |      |
|   |               |      |
| ***************************************   |               |      |
| *********   |               |      |
|   |               |      |
| ***************************************   |               |      |
|   | More info     | >    |
| Plate changes   |               |      |
| See in this check if this HYUNDAI had different number plates.  |               |      |
| Number of plates  |               | ,    |
| Current registration  | UK CONTRACTOR |      |
| Plate since   |               |      |
| Current registration  | UK UK         |      |
| Plate since   |               |      |
|   | More info     | >    |
|   |               |      |

CarCheck.co.uk page 7/10



report date: 2024-03-28

### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 6          |
| First mileage registration | 2018-06-06 |
| Last registration          | 2023-06-28 |
| Complete history           | See info   |



| Registration #1 | 2018-06-06 | 15 mi     |
|-----------------|------------|-----------|
| Registration #2 |            | 11.777 es |
| Registration #3 | 2021-06-30 | 11.942 mi |
| Registration #4 |            | 11.777 es |
| Registration #5 |            | 11.777 es |
| Domintuntion #C |            |           |

Registration #6

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| 50501 |                  |
| 50566 |                  |
| 50567 |                  |
| 50569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 91%             |
| Children       | 80%             |
| Pedestrian     | 70%             |
| Safety systems | 82%             |
| Overall rating | 83%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1820 mm |
|---------------------|---------|
| Height              | 1450 mm |
| Length              | 4470 mm |
| Wheel base          | 2700 mm |
| Kerb weight         | 1370 kg |
| Max. allowed weight | 1870 kg |

### Additional information

| Fuel tank capacity                | 45 I             |            |
|-----------------------------------|------------------|------------|
| Fuel delivery                     | Direct Injection |            |
| Number of doors                   | 5                |            |
| Number of seats<br>CarCheck.co.uk | 5                | page 10/10 |

Number of axles 2

**Engine number** G4LEHU531671