





report date: 2024-03-28

## General information

| Make                | PEUGEOT        |
|---------------------|----------------|
| Model               | RCZ THP GT     |
| Colour              | Black          |
| Year of manufacture | 2010           |
| Top speed           | 134 mph        |
| 0 - 60 mph          | 8.3 seconds    |
| Gearbox             | 6 speed Manual |

## Engine & fuel consumption

| Power                   | 156 BHP             |
|-------------------------|---------------------|
| Max. torque             | 240 Nm at 1.400 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 30.4 mpg            |
| Consumption extra urban | 54.3 mpg            |
| Consumption combined    | 42.2 mpg            |
| CO2 emission            | 155 g/km            |
| CO2 label               | G                   |



CarCheck.co.uk page 1/13



report date: 2024-03-28


## Internet history


## Entry 1

Date 2021-07-22

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## MOT history

| MOT expiry date    | 2024-11-05 |
|--------------------|------------|
| MOT pass rate      | 73 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 4          |
| Total advice items | 11         |
| Total items failed | 13         |

| MOT #15                 |   | 2023-11-06 18:35 |
|-------------------------|---|------------------|
| MOT test                | number  | 741381300333     |
| Result                  |   | ✓ Passed         |
| Next expiry date 2024-1 |   | 2024-11-05       |
| Advice                  | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |
| Advice                  | Oil leak, but not excessive (8.4.1 (a) (i))                                 |                  |

| MOT #14  |   | 2023-11-06 18:35 |
|--|---|------------------|
| MOT test number  |   | 790205829644     |
| Result   |   | <b>X</b> Failed  |
| Pass with rectification  | Offside Stop lamp(s) not working (4.3.1 (a) (ii))               |                  |
| Advice Oil leak, but not   | excessive (8.4.1 (a) (i))                                       |                  |
| Pass with rectification  | Offside Front Headlamp aim too far to the right (4.1.2 (a))     |                  |
| Pass with rectification  | Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) |                  |
| Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |   |                  |
| Pass with rectification  | Nearside Front Headlamp not working on main beam (4.1.1 (a)     | (ii))            |

CarCheck.co.uk page 3/13



report date: 2024-03-28

**X** Failed

 MOT #13
 2022-11-03 09:40

 MOT test number
 413168974216

Advice

Result

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #12** 2022-11-03 09:40

**MOT test number** 643396955309

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

..... (-, (-, ,

Pass with rectification Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #11** 2021-07-02 14:23

**MOT test number** 226347806413

Result \( \sqrt{Passed} \)

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10 2019-09-25 07:26

**MOT test number** 655694593936

**Result** ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

| MOT #9                                     | 2019-09-24 11:07   |
|--|--|
| MOT test number                            | 396143860583   |
| Result                                     | <b>★</b> Failed  |
| Fail Nearside Rear Position lamp no        | ot working light cluster defective (4.2.1 (a) (ii))                    |
| Fail Road wheel fixing missing one         | bolt missing on all 4 wheels (5.2.1 (a) (i))                           |
| Fail Offside Headlamp not working          | on dipped beam (4.1.1 (a) (ii))  |
| Fail Nearside Stop lamp(s) not wor         | king lamp cluster defective (4.3.1 (a) (ii))                           |
| Fail Offside Front Coil spring fractu      | red or broken (5.3.1 (b) (i))  |
| Fail Offside Headlamp aim not test         | ed (4.1.2 (b))   |
| Minor Nearside Registration plate (b) (i)) | lamp inoperative in the case of multiple lamps or light sources (4.7.1 |

| (b) (i))        |                  |
|-----------------|------------------|
|                 |                  |
| MOT #8          | 2018-08-02 16:58 |
| MOT test number | 251640946465     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #7          | 2017-09-15 11:22 |
| MOT test number | 545728101528     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #6          | 2016-09-20 08:46 |
| MOT test number | 230771438281     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #5          | 2015-09-23 09:31 |
| MOT test number | 682943135234     |
| Result          | ✓ Passed         |

**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit Inner edge (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit Inner edge (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-28

× Failed

MOT #4 2014-12-24 09:54

**MOT test number** 179658654388

Result ✓ Passed

MOT #3 2014-12-20 09:02

**MOT test number** 825274454320

Result Passed

**Notice** N/s/fr tyre sidewall kirbing

MOT #2 2013-11-04 16:43

**MOT test number** 925098003374

Result ✓ Passed

MOT #1 2013-11-04 09:22

728088703379 **MOT test number** 

Result

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 6/13



report date: 2024-03-28

## Tax & MOT check



| Tax status       | Valid until 1 May |
|------------------|-------------------|
| Days left        | 1                 |
| MOT expiry date  | 5 November 2024   |
| Full MOT history | See MOT history   |

## Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

| Owner | history |
|-------|---------|

| o mier mistery   |             |
|--|-------------|
| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. |             |
|  |             |
|  |             |
| ***************************************  |             |
|  |             |
| ********   |             |
| ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,  |             |
| ***************************************  |             |
| Plate changes  | More info > |
| See in this check if this PEUGEOT had different number plates.   |             |
| Number of plates   |             |
| Current registration   | NIX.        |
| Plate since  |             |
| Current registration   | UK UK       |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 10/13



report date: 2024-03-28

## Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 17         |
| First mileage registration | 2010-09-23 |
| Last registration          | 2023-11-06 |
| Complete history           | See info   |



| Registration #1                                    | 2010-09-23 | 22 mi  |
|--|------------|--|
| Registration #2                                    | 2013-11-04 | 24.937 mi  |
| Registration #3                                    | 2013-11-04 | 24.937 mi  |
| Registration #4                                    | 2014-12-20 | 38.376 mi  |
| Registration #5                                    | 2014-12-24 | 38.427 mi  |
| Registration #6                                    | 2015-09-23 | 44.186 mi  |
| Registration #7                                    | 2016-09-20 | 51.422 mi  |
| Registration #8                                    | 2017-09-15 | 60.386 mi  |
| Registration #9                                    | 2018-08-02 | 67.210 mi  |
| Registration #10                                   |            | 11.117 au  |
|  |            |  |
| Registration #11                                   |            | 11.777 es  |
| Registration #11 Registration #12                  |            | 11.777 es  |
|  |            | 11.777 es<br>11.777 es<br>11.777 es                                |
| Registration #12                                   |            | 11.777 es<br>11.777 es<br>11.777 es                                |
| Registration #12 Registration #13                  |            | 11,777 es<br>11,777 es<br>11,777 es<br>11,777 es                   |
| Registration #12 Registration #13 Registration #14 |            | 11,777 esi<br>11,777 esi<br>11,777 esi<br>11,777 esi<br>11,777 esi |

More info >

CarCheck.co.uk page 12/13



EX600WK report date: 2024-03-28

Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 |                 |
| 50482 |                 |
| 60501 |                 |
| 60566 |                 |
| 60567 |                 |
| 50569 |                 |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 82%             |
| Children       | 81%             |
| Pedestrian     | 53%             |
| Safety systems | 83%             |
| Overall rating | 76%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 2107 mm |
|---------------------|---------|
| Height              | 1352 mm |
| Length              | 4290 mm |
| Kerb weight         | 1350 kg |
| Max. allowed weight | 1740 kg |

# Additional information

| Fuel tank capacity                | 55 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 2                     |
| Number of seats                   | 4                     |
| Number of axles<br>CarCheck.co.uk | 2 page 13/13          |

**Engine number** 

FJBD0799390