





report date: 2024-03-28

### General information

Make	CITROEN
Model	DS3 PURETECH FLAIR
Colour	Blue
Year of manufacture	2015
Top speed	106 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	80 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/12



## Internet history

#### Entry 2

Date	2022-11-14
Pictures	0
Listing price	View report

#### source: carcraft.co.uk

#### Entry 1

Date	2022-07-06	
Pictures	15	
Listing price	<u>View report</u>	









source: cargurus.co.uk

CarCheck.co.uk page 2/12



	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-04-11
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	23
Total items failed	1

MOT #9	2024-04-12 12:06
MOT test number	264051078555
Result	✓ Passed
Next expiry date	2025-04-11
Advice Rear Exhaust mounting defective (6.1.2 (a))	

MOT #8	2024-04-12 12:06
MOT test number	609044005666
Result	<b>X</b> Failed
Advice Rear Exhaust mounting defective (6.1.2 (a))	
Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))	

MOT #7	2023-08-04 10:47
MOT test number	146414086716
Result	✓ Passed
Advice Rear Exhaust mounting of	lefective (6.1.2 (a))
Advice Offside Rear Inner Brake	pad(s) wearing thin (1.1.13 (a) (ii))
Advice Oil leak, but not excessiv	e engine (8.4.1 (a) (i))
Minor Offside Windscreen wiper	blade defective (3.4 (b) (i))

CarCheck.co.uk page 3/12



CK64UJO

report date: 2024-03-28

**MOT** #6 2022-08-06 11:32

**MOT** test number 511293865608

Result ✓ Passed

**MOT #5** 2022-01-14 12:13

**MOT** test number 327759325922

Result ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #4** 2021-01-11 12:27

**MOT** test number 963905461281

Result Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Exhaust mounting defective (6.1.2 (a))

**Advice** Nearside Front Tyre slightly damaged inner sidewall (5.2.3 (d) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT** #3 2020-01-14 12:07

**MOT** test number 955668766105

Result Passed

**Advice** Rear Tyre worn close to legal limit/worn on edge N/s = 1.78mm O/s = 1.98mm (5.2.3 (e))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



MOT #2 2019-01-09 11:55

MOT test number 214767688281

Result \( \sqrt{Passed} \)

**Advice** Rear tyres perishing

**Advice** N/s front tyre cut outer side wall

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** O/s rear brake disc corroded

**MOT #1** 2018-01-11 13:35

MOT test number 139930543137

Result \square Passed

Advice Nearside Front Tyre On Legal Limit 1.6mm & Cut In Outer Sidewall Not Exposing Cords Or Ply 205

45 17 88V Extra Load Michelin (4214

Advice Engine Covers Fitted & Outer Sills Covered Obscuring Some Components From Inspection

**Advice** Front Lower Both Suspension Arm Rear Bushes Starting To Deteriorate But Not Resulting In

**Excessive Movement** 

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	11 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



$\alpha$	ner	hict	001
UVV	пег	msi	$\mathbf{o} \mathbf{v}$
		11100	<b>U</b> 1

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
THE STATE OF THE S	
***************************************	
**************	
********	
***************************************	
THE STREET STREET	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	IK SIN
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-01-15
Last registration	2024-04-12
Complete history	See info



Registration #1	2015-01-15	22 mi
Registration #2	2018-01-11	14.974 mi
Registration #3	2019-01-09	26.121 mi
Registration #4	2020-01-14	34.228 mi
Registration #5	2021-01-11	40.837 mi
Registration #6	2022-01-14	49.541 mi
Registration #7		11.777 es
Registration #7 Registration #8		0.77 46
		11.777 es 11.777 es 11.777 es
Registration #8		10,777 est 10,777 est 10,777 est
Registration #8 Registration #9		10,777 est 10,777 est 10,777 est 10,777 est

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



# Dimensions & weight

Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	965 kg
Max. allowed weight	1500 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B2150067940

CarCheck.co.uk page 12/12