



RENAULT

YH16KKC

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC LL29 BUSINESS ENERGY DCI
Colour	Black
Year of manufacture	2016
Top speed	105 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-06-21
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-02
MOT pass rate	50 %
MOT passed	5
Failed MOT tests	5
Total advice items	28
Total items failed	2

MOT #10	2023-09-28 14:58
MOT test number	972669632604
Result	✓ Passed
Next expiry date	2024-10-02

MOT #9	2023-09-13 09:06
MOT test number	134341683926
Result	✗ Failed
MAJOR	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
MAJOR	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
MAJOR	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #8	2022-09-29 12:03
MOT test number	546918066076
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7** 2022-09-28 09:17**MOT test number** 596865581140**Result** ✗ Failed**DANGEROUS** Offside Rear Coil spring missing and directional control affected (5.3.1 (c) (ii))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Rear Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Offside Rear Other passenger door does not latch securely closed (6.2.3 (a))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**MOT #6** 2021-09-15 08:32**MOT test number** 154602138406**Result** ✓ Passed**MOT #5** 2021-09-14 12:31**MOT test number** 228241636682**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**DANGEROUS** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

**MOT #4** 2020-09-23 11:37**MOT test number** 918301379849**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2020-09-23 11:37**MOT test number** 566107825428**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #2** 2019-04-03 07:39**MOT test number** 827770322662**Result** ✓ Passed



MOT #12019-03-27 13:36

MOT test number994076384541

Result

Failed

- Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- MAJOR

Central Seat belt buckle not functioning as intended middle bench offside seat inner buckle (red one) (7.1.2 (d))
- MAJOR

Nearside Rear Seat belt buckle not functioning as intended rear bench nearside seat inner buckle (7.1.2 (d))
- MAJOR

Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR

Nearside Seat belt buckle damaged middle bench nearside seat outer buckle (7.1.2 (d))
- MAJOR

Offside Seat belt buckle damaged middle bench offside seat outer buckle (7.1.2 (d))
- MAJOR

Brake pedal anti-slip provision worn smooth (1.1.2 (c))



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
2 October 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	YH16KKC
Plate since	2019-03-29
Current registration	YH16KKC
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-03-29
Last registration	2023-09-28
Complete history	See info



Registration #1	2016-03-29	16 mi
Registration #2	2019-03-27	111.403 mi
Registration #3	2019-04-03	111.403 mi
Registration #4	2020-09-23	115.214 mi
Registration #5	2020-09-23	115.214 mi
Registration #6	2023-09-28	115.214 mi
Registration #7	2023-09-28	115.214 mi
Registration #8	2023-09-28	115.214 mi
Registration #9	2023-09-28	115.214 mi
Registration #10	2023-09-28	115.214 mi
Registration #11	2023-09-28	115.214 mi
Registration #12	2023-09-28	115.214 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5399 mm
Kerb weight	1923 kg
Max. allowed weight	3020 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Number of axles	2

