



report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D3 R-DESIGN
Colour	Black
Year of manufacture	-
Top speed	134 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg



**MOT history**

<b>MOT #10</b>	2020-11-06 11:18
<b>MOT test number</b>	519893217506
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-11-08

<b>MOT #9</b>	2019-05-09 10:48
<b>MOT test number</b>	411368933969
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2018-05-08 14:34
<b>MOT test number</b>	307178619769
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2018-04-09 11:30
<b>MOT test number</b>	152655454638
<b>Result</b>	✓ Passed

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

<b>MOT #6</b>	2017-04-21 09:02
<b>MOT test number</b>	496243742832
<b>Result</b>	✓ Passed

**Advice** Offside Front Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2017-04-20 13:10**MOT test number** 489301210978**Result** ✗ Failed**Advice** Offside Front Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2016-05-06 10:09**MOT test number** 114285512755**Result** ✓ Passed**MOT #3** 2015-05-28 15:58**MOT test number** 155118345155**Result** ✓ Passed**MOT #2** 2015-05-27 16:58**MOT test number** 796647145175**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Nearside front tyre bald on inner edge**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2014-06-13 11:30**MOT test number** 586844764118**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>DA11UYP</b>
Plate since	2019-03-28
Current registration	<b>DA11UYP</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2011-06-24
Last registration	2020-11-06
Complete history	<a href="#">See info</a>



Registration #1	2011-06-24	21 mi
Registration #2	2014-06-13	51.228 mi
Registration #3	2015-05-27	67.805 mi
Registration #4	2015-05-28	67.805 mi
Registration #5	2016-05-06	77.722 mi
Registration #6	2017-04-20	82.452 mi
Registration #7	2019-05-20	95.277 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi

More info >





Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1685 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1061345