



PEUGEOT



LOI2AWG

report date: 2024-03-28

General information

Make	PEUGEOT
Model	508 HDI ACTIVE
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	110 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-03
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-23
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	35
Total items failed	2

MOT #14 2024-04-18 12:48

MOT test number 363404415059

Result ✓ Passed

Next expiry date 2025-04-23

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both rear brake discs are getting low and are corroded an in poor condition (1.1.14 (a) (ii))
- Advice** Front Outer Brake pad(s) wearing thin both front outer brake pads are slightly more worn than the inner pads (1.1.13 (a) (ii))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Both front fog lights not working
- Advice** Rear Brake pad(s) wearing thin rear brake pads are getting low (1.1.13 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn to 3mm and is also wearing on the inner edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #13 2023-04-24 09:12

MOT test number 745330264132

Result ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12** 2023-04-21 09:15**MOT test number** 773080544060**Result** ✗ Failed**MAJOR** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MAJOR** Offside Windscreen washer not working (3.5 (a))**MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Nearside Windscreen washer not working (3.5 (a))**MOT #11** 2022-03-26 11:14**MOT test number** 832558281875**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #10** 2022-03-25 10:43**MOT test number** 825129220100**Result** ✗ Failed**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Nail in tyre**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #9** 2021-04-22 14:46**MOT test number** 255563107419**Result** ✓ Passed

**MOT #8** 2021-04-22 13:41**MOT test number** 536641147665**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre has ply or cords exposed cut to outer sidewall 215 60 16 (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking and perishing 215 60 16 (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.5/3mm 215 60 16 (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm 215 60 16 (5.2.3 (e))**Advice** Offside Rear Nail in tyre marked yellow**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking and perishing 215 60 16 (5.2.3 (d) (ii))**Minor** Offside Rear Tyre obviously under inflated (5.2.3 (l))**MOT #7** 2019-08-01 10:10**MOT test number** 573310991192**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 3mm with outer wall cracking slightly (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 2.5mm limit is 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e))**MOT #6** 2018-07-09 08:10**MOT test number** 465710555992**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**MOT #5** 2017-07-04 08:58**MOT test number** 641995551652**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 3mm & cracking in tread (4.1.E.1)

**MOT #4** 2016-07-05 11:44**MOT test number** 250916260159**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-07-05 10:30**MOT test number** 243692265250**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Engine oil level high**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2015-06-17 12:06**MOT test number** 748428765184**Result** ✓ Passed**MOT #1** 2015-06-16 13:04**MOT test number** 277937765184**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 April 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	23 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	LO12AWG
Plate since	2019-03-28
Current registration	LO12AWG
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-07-04
Last registration	2024-04-18
Complete history	See info



Registration #1	2012-07-04	7 mi
Registration #2	2015-06-16	39.014 mi
Registration #3	2015-06-17	39.015 mi
Registration #4	2016-07-05	47.733 mi
Registration #5	2016-07-05	47.733 mi
Registration #6	2017-07-04	55.378 mi
Registration #7	2018-07-09	62.786 mi
Registration #8	2019-08-01	71.687 mi
Registration #9	2020-08-01	71.687 mi
Registration #10	2021-08-01	71.687 mi
Registration #11	2022-08-01	71.687 mi
Registration #12	2023-08-01	71.687 mi
Registration #13	2024-08-01	71.687 mi
Registration #14	2025-08-01	71.687 mi
Registration #15	2026-08-01	71.687 mi
Registration #16	2027-08-01	71.687 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1498 mm
Length	4276 mm
Wheel base	2608 mm
Kerb weight	1410 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JBEE0158928