





report date: 2024-03-28

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Black
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	550 Nm at 1.500 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.8 mpg
CO2 emission	260 g/km
CO2 label	М



CarCheck.co.uk page 1/13



Internet history

Entry 3


Date 2021-12-12

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-07-30
Pictures	28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2023-07-31
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	16
Total items failed	11

MOT #16	2022-08-01 15:52
MOT test number	120374477494
Result	✓ Passed
Next expiry date	2023-07-31

MOT #15	2021-07-29 10:25
MOT test number	280556601386
Result	✓ Passed
Advice Rear wiper Blade missing	

MOT #14	2021-06-17 09:20
MOT test number	311147515639
Result	X Failed
Fail Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d)) Minor Offside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Advice Rear wiper Blade missing	
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/13



MOT #13 2020-10-08 10:40

MOT test number 582180096944

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12 2020-09-30 11:03

MOT test number 161041308947

Result X Failed

Fail Front Windscreen wiper not working (3.4 (a))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Driver's door cannot be opened from outside the vehicle (6.2.3 (a))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #11 2018-03-17 14:01

MOT test number 723048890160

Result ✓ Passed

MOT #10 2017-03-07 10:59

MOT test number 536915615801

Result

Passed

Advice Oil leak

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/13



MOT #9 2017-03-04 12:07

MOT test number 385663825729

Result X Failed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened Lipped ASAP needs changed (3.5.1i)

Fail Offside Front Headlamp not working on dipped beam (1.7.5a)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Oil leak

Advice EML ON

Fail Offside Front Headlamp not working on main beam (1.7.5a)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #8 2016-01-26 11:25

MOT test number 402550639127

Result ✓ Passed

MOT #7 2015-01-27 11:11

MOT test number 339177525097

MOT #6 2015-01-19 12:51

MOT test number 138349515494

Result × Failed

Fail Nearside Headlamp aim too low (1.8)

Notice Bonnet safety catch sticking

Fail Offside Steering rack gaiter insecure (2.2.D.2d)

Notice Off side front brake hose not located in mounting bracket

CarCheck.co.uk page 5/13



MOT #5 2014-02-03 14:18

MOT test number 147714634081

MOT #4 2012-12-18 14:50

MOT test number 967953452376

Result ✓ Passed

MOT #3 2012-12-17 11:09

MOT test number 347382552300

Result X Failed

Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #2 2012-08-28 10:40

MOT test number 258571042299

Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #1 2011-08-17 11:20

MOT test number 999629921200

Result \(\sqrt{Passed} \)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)

Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 6/13



Tax & MOT check



X MOT

Tax expired: 31 August 2023

Tax status

Expired:
31 July 2023

Expired at 31 August 2023

Days left 242 days too late

MOT expiry date 31 July 2023

Full MOT history See MOT history

Tax calculation

Vehicle class	49
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



L7MPX

report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
manus .	

manus .	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	UK NE
Plate since	
Current registration	UK NE
Finite since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-06-17
Last registration	2022-08-01
Complete history	See info



Registration #1	2008-06-17	10 mi
Registration #2	2011-08-17	58.695 mi
Registration #3	2012-08-28	75.152 mi
Registration #4	2012-12-17	79.347 mi
Registration #5	2012-12-18	79.386 mi
Registration #6	2014-02-03	80.061 mi
Registration #7	2015-01-19	90.678 mi
Registration #8	2015-01-27	90.678 mi
Registration #9	2016-01-26	92.360 mi
Registration #10	2017-03-04	165.599 mi
Registration #11		11.777 es
Registration #12		11.117 es
Registration #13		11.177 mi
Registration #14		11.177 es
Registration #15		11.777 es
Registration #16		D 207 au
3		
Registration #17		11.777 es
-		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles 2

Engine number CAS 025689