



report date: 2024-03-28

General information

Make	CITROEN
Model	C4 PURETECH PLATINUM
Colour	Black
Year of manufacture	2016
Top speed	108 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	B






Internet history

Entry 2

Date	2021-03-01
Pictures	16
Listing price	<a href="#">View report</a>



source: yesauto.com




Entry 1

Date	2021-03-01
Pictures	10
Listing price	<a href="#">View report</a>



source: yesauto.com





## MOT history

MOT expiry date	2025-02-26
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	24
Total items failed	5

## MOT #9 2024-02-26 14:56

MOT test number 985648528447

Result ✓ Passed

Next expiry date 2025-02-26

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D BUSH (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D BUSH (5.3.4 (a) (i))
- Advice** Front exhaust flexi section deteriorated

## MOT #8 2023-02-27 13:05

MOT test number 151332891812

Result ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7**

2022-01-27 10:46

**MOT test number**

764279186239

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Exhaust mounting defective (6.1.2 (a))

**MOT #6**

2022-01-27 10:08

**MOT test number**

949704216321

**Result**

✗ Failed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure 205 50 17 (5.2.3 (d) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Exhaust mounting defective (6.1.2 (a))

**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure 205 50 17 (5.2.3 (d) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #5**

2021-01-21 15:27

**MOT test number**

430005517069

**Result**

✓ Passed

**MOT #4** 2021-01-21 12:06**MOT test number** 260585597931**Result** ✗ Failed

**Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**MOT #3** 2020-01-20 14:45**MOT test number** 225050551694**Result** ✓ Passed

**Advice** Central Front exhaust bracket beginning to corrode away and split however still secure at present

**MOT #2** 2020-01-20 09:52**MOT test number** 188181053809**Result** ✗ Failed

**Advice** Both front wipers worn and smearing however still clearing screen

**Advice** Central Front exhaust bracket beginning to corrode away and split however still secure at present

**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #1** 2019-01-24 10:21**MOT test number** 611498826221**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
26 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	26 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-01-25
Last registration	2024-02-26
Complete history	<a href="#">See info</a>



Registration #1	2016-01-25	6 mi
Registration #2	2019-01-24	51.636 mi
Registration #3	2020-01-20	56.739 mi
Registration #4	2020-01-20	56.739 mi
Registration #5	2021-01-21	61.750 mi
Registration #6	2021-01-21	61.750 mi
Registration #7	2022-01-20	61.750 mi
Registration #8	2022-01-20	61.750 mi
Registration #9	2022-01-20	61.750 mi
Registration #10	2022-01-20	61.750 mi
Registration #11	2022-01-20	61.750 mi
Registration #12	2024-02-26	61.750 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1728 mm
Height	1514 mm
Length	3944 mm
Wheel base	2451 mm
Kerb weight	975 kg
Max. allowed weight	1525 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B2150242811