





report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 HDI SPORT
Colour	Black
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	76.4 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-10


Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



KS10BBO report date: 2024-03-28

MOT history

MOT expiry date	2024-05-29
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	16
Total items failed	11

MOT #16	2023-05-30 11:13
MOT test number	855077381949
Result	✓ Passed
Next expiry date 2024-05-	
Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #15		2022-01-19 08:23
MOT test	number	704779165417
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor (i)) Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)		

MOT #14	2021-02-01 13:57
MOT test number	706547930348
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Headlamps Misting

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2020-07-17 09:37 **MOT** test number 741909259608 Result × Failed **Advice** Front Headlamps Misting Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a)) Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) **Fail Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Front Windscreen washer not working (3.5 (a)) Fail Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

 MOT #11
 2019-08-01 12:15

 MOT test number
 111677144655

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #10 2019-08-01 10:58

MOT test number 405450087519

Result X Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #9 2018-07-27 14:32

MOT test number 448254243334

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2018-07-27 14:32

MOT test number 509429606436

Result X Failed

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2017-08-01 15:38

MOT test number 831401434916

Result \(\sqrt{Passed} \)

Advice Nearside front brake disc worn/corroded inner face

Advice Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit 2mm (4.1.E.1)

MOT #6 2016-07-29 15:14

MOT test number 838037311338

Result

Passed

Advice Engine oil level low

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #5		2016-07-29 15:14
MOT test number		342987447437
Result		X Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	
Advice Engine oil level	low	
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	

MOT #4		2015-07-31 15:06
MOT test number		758262615297
Result		✓ Passed
MOT #3		2015-07-31 15:06
MOT test number		128212515223
Result		X Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)	

MOT #2	2014-07-26 12:27
MOT test number	745327304254
Result	✓ Passed
MOT #1	2013-07-15 08:28
MOT test number	575484493115
Result	✓ Passed

CarCheck.co.uk page 6/13



KS10BBO report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	29 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. about of pliates factor scincol

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-14
Last registration	2023-05-30
Complete history	See info



Registration #1	2010-06-14	11 mi
Registration #2	2013-07-15	45.913 mi
Registration #3	2014-07-26	55.626 mi
Registration #4	2015-07-31	62.642 mi
Registration #5	2016-07-29	72.023 mi
Registration #6	2016-07-29	72.023 mi
Registration #7	2017-08-01	81.748 mi
Registration #8	2018-07-27	91.017 mi
Registration #9	2018-07-27	91.017 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		D.327 es

More info >

CarCheck.co.uk page 12/13




report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4037 mm
Wheel base	2540 mm
Kerb weight	1280 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	e 13/13

Number of axles 2

Engine number JBBX3107748