



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S COUPE CABRIOLET
Colour	Silver
Year of manufacture	-
Top speed	119 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-14
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #17 2022-07-13 08:07

MOT test number 599316852655

Result ✓ Passed

Next expiry date 2023-07-26

**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Rear Passenger seat(s) missing at time of test

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))



MOT #16

2022-07-11 16:04

MOT test number

134999672901

Result

✗ Failed

**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Rear Service brake excessively fluctuating (1.2.1 (e))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Nail in tyre**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))

MOT #15

2021-07-27 12:19

MOT test number

316354973069

Result

✓ Passed



MOT #14	2021-07-27 12:19
MOT test number	718852046526
Result	✗ Failed
Pass with rectification	Front Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))

MOT #13	2020-09-18 12:56
MOT test number	167486522560
Result	✓ Passed
Advice	Rear Passenger seat(s) missing at time of test 3rd row of seat / seat belts not tested
Advice	Offside Rear Tyre slightly damaged/cracking or perishing heavily cracking in tread (5.2.3 (d) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge n/s & o/s (5.2.3 (e))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output n/s & o/s (4.1.4 (b))

**MOT #12**

2020-09-18 08:39

**MOT test number**

675821999279

**Result****✗ Failed**

- DANGEROUS** Nearside Rear Outer Passenger's seat insecure fixing point (6.2.6 (a) (ii))
- MAJOR** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing heavily cracking in tread (5.2.3 (d) (ii))
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Minor** Nearside Front Windscreen wiper blade defective slightly smeary (3.4 (b) (i))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge n/s & o/s (5.2.3 (e))
- Advice** Rear Passenger seat(s) missing at time of test 3rd row of seat / seat belts not tested
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output n/s & o/s (4.1.4 (b))
- Minor** Offside Rear Upper Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #11**

2019-09-19 09:36

**MOT test number**

825780494760

**Result****✓ Passed**

- Advice** Offside Front Play in steering rack inner joint(s)
- Minor** Nearside Rear Upper Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** 3rd row of seats not fitted at time of test
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2018-09-20 08:32**MOT test number** 425533518967**Result** ✓ Passed**MOT #9** 2017-09-20 10:09**MOT test number** 261630482484**Result** ✓ Passed**MOT #8** 2016-09-21 10:15**MOT test number** 291138299424**Result** ✓ Passed**MOT #7** 2015-09-04 10:23**MOT test number** 672625283647**Result** ✓ Passed

**Advice** Offside Front Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #6** 2014-09-23 10:07**MOT test number** 675546864287**Result** ✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2013-09-10 10:51**MOT test number** 589363853208**Result** ✓ Passed

**MOT #4** 2012-08-24 14:19**MOT test number** 969947732293**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-08-30 13:04**MOT test number** 698322641247**Result** ✓ Passed**Notice** Both rear and n/s centre seats removed**MOT #2** 2010-09-01 11:31**MOT test number** 760084440283**Result** ✓ Passed**Notice** N/s/rear seats removed**MOT #1** 2009-09-24 12:43**MOT test number** 601427569284**Result** ✓ Passed





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-11-15
Last registration	2022-07-13
Complete history	<a href="#">See info</a>



Registration #1	2006-11-15	8 mi
Registration #2	2009-09-24	8.355 mi
Registration #3	2010-09-01	13.104 mi
Registration #4	2011-08-30	16.985 mi
Registration #5	2012-08-24	22.266 mi
Registration #6	2013-09-10	32.056 mi
Registration #7	2014-09-23	40.658 mi
Registration #8	2015-09-04	49.752 mi
Registration #9	2016-09-21	56.797 mi
Registration #10	2017-09-20	64.301 mi
Registration #11	2018-09-20	71.301 mi
Registration #12	2019-09-20	78.301 mi
Registration #13	2020-09-20	85.301 mi
Registration #14	2021-09-20	92.301 mi
Registration #15	2022-09-20	99.301 mi
Registration #16	2023-09-20	106.301 mi
Registration #17	2024-09-20	113.301 mi
Registration #18	2025-09-20	120.301 mi
Registration #19	2026-09-20	127.301 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1528 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	FX6P2862643