





report date: 2024-03-29

General information

Make	MINI
Model	ONE AUTO COOPER
Colour	Red
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

F	n	+	rv	,	2
드	ш	L	ΙV	,	_

Date	2021-08-09
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

Life y 1	
Date	2021-08-04
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



AV62WSO report date: 2024-03-29

MOT history

MOT expiry date	2024-09-19
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	15
Total items failed	5

MOT #11		2023-09-18 13:17
MOT test	number	437668976763
Result		✓ Passed
Next expi	ry date	2024-09-19
Advice	Front Tyre has a cut but not deep enough to reach the ply or cords both	(5.2.3 (d) (i))
Advice	Nearside Front bracket damage	
Advice	Nearside Headlamp has a product on the lens but not seriously reducing	light output (4.1.4 (b))

MOT #10		2022-09-13 13:08
MOT test	number	638820668757
Result		✓ Passed
Advice	Front Outer Tyre has a cut but not deep enough to reach the ply or cord	ds Both (5.2.3 (d) (i))
Advice	Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Minor	Nearside Side repeater insecure (4.4.1 (c) (i))	
Advice	Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))	

CarCheck.co.uk page 3/12



AV62WSO report date: 2024-03-29

MOT #9 2022-09-13 11:17

MOT test number 215008236391

Result X Failed

Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

Minor Nearside Side repeater insecure (4.4.1 (c) (i))

Fail Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

Advice Front Outer Tyre has a cut but not deep enough to reach the ply or cords Both (5.2.3 (d) (i))

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Fail Spare wheel insecure in carrier (6.1.5 (b) (i))

MOT #8 2021-09-20 15:46

MOT test number 938079613426

Result ✓ Passed

MOT #7 2021-09-17 10:15

MOT test number 242647231793

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2020-12-23 10:45

MOT test number 743916060794

Result / Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5	2019-12-09 13:07
MOT test number	882024566827
Result	✓ Passed
MOT #4	2018-12-31 11:35
MOT test number	946719191357
Result	✓ Passed
MOT #3	2017-11-29 11:13
MOT test number	143939067390
Result	✓ Passed
MOT #2	2016-12-15 10:46
MOT test number	397405970899
Result	✓ Passed
Advice Nearside front and rear bumper damaged	

MOT #1	2015-11-09 15:01
MOT test number	793396848414
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check





Expires: 19 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	19 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



AV62WSO
report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	IK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-11-20
Last registration	2023-09-18
Complete history	See info



Registration #1	2012-11-20	11 mi
Registration #2	2015-11-09	12.335 mi
Registration #3	2016-12-15	16.202 mi
Registration #4	2017-11-29	23.333 mi
Registration #5	2018-12-31	27.113 mi
Registration #6	2019-12-09	35.700 mi
Registration #7	2020-12-23	39.194 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.177 esi

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1105 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberB081J342