





report date: 2024-03-28

General information

Make	ТОУОТА
Model	URBAN CRUISER VVT-I
Colour	Silver
Year of manufacture	2010
Top speed	109 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.329 сс
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 3

Date 2021-08-09

Pictures 15

Listing price <u>View report</u>










source: autotrader.co.uk


Entry 2

Date 2021-07-12

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-06-26

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



SG60PSY report date: 2024-03-28

MOT history

MOT expiry date	2024-06-29
MOT pass rate	100 %
MOT passed	11
Failed MOT tests	0
Total advice items	14
Total items failed	0

MOT #11	2023-06-18 11:08
MOT test number	846119934511
Result	✓ Passed
Next expiry date	2024-06-29
Advice Nearside Front Lower Suspension arm pin or bush worn but not result (5.3.4 (a) (i))	ting in excessive movement

MOT #10	2022-06-19 10:25
MOT test number	842613829061
Result	✓ Passed
Advice Rear Coil spring corroded both (5.3.1 (b) (i))	

MOT #9		2021-06-30 09:29
MOT test	number	858772943391
Result		✓ Passed
Advice	Brake pipe corroded, covered in grease or other material all (1.1.11 (c))	
Advice	Nearside Rear Fuel Pipe/s corroded	
Advice	Front Suspension component corroded but not seriously weakened offside and	d nearside (5.3.3 (b)
Advice	Rear Coil spring corroded offside and nearside (5.3.1 (b) (i))	
Advice (5.3.4 (a) (Nearside Front Lower Suspension arm pin or bush worn but not resulting in ex	cessive movement

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

268319258949

Result

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #7	2019-08-1	4 10:24
MOT test	number 313154	007033
Result		Passed
Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Nearside Front slight play at near side track rod	

MOT #6	2018-08-15 10:22
MOT test number	337816664631
Result	✓ Passed
MOT #5	2017-08-23 13:47
MOT test number	920070335850
Result	✓ Passed

MOT #4		2016-08-16 12:53
MOT test n	umber	936198810265
Result		✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weake	ned (3.5.1i)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3	2015-08-17 13:29
MOT test number	368880213975
Result	✓ Passed
MOT #2	2014-08-18 13:41
MOT test number	858790234206
Result	✓ Passed
MOT #1	2013-08-19 14:55
MOT test number	305091633286
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this TOYOTA had different number plates. about of pliates factor scincore

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-13
Last registration	2023-06-18
Complete history	See info



Registration #1	2010-09-13	16 mi
Registration #2	2013-08-19	16.580 mi
Registration #3	2014-08-18	22.696 mi
Registration #4	2015-08-17	28.801 mi
Registration #5	2016-08-16	34.560 mi
Registration #6	2017-08-23	39.078 mi
Registration #7	2018-08-15	43.539 mi
Registration #8	2019-08-14	47.941 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight

Width	1725 mm
Height	1525 mm
Length	3930 mm
Wheel base	2460 mm
Kerb weight	1150 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 1NR0263253