



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SHARAN SE (115BHP)
Colour	Silver
Year of manufacture	2005
Top speed	107 mph
0 - 60 mph	17.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	115 BHP
Max. torque	170 Nm at 2.600 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	19.1 mpg
Consumption extra urban	32.5 mpg
Consumption combined	25.7 mpg
CO2 emission	259 g/km
CO2 label	M






Internet history


Entry 2

Date	2022-05-01
Pictures	9
Listing price	View report



Video viewing
Book a video viewing with one of our team.
See the vehicle from the comfort of your own home.

[Visit our website for more info](#)





source: cargurus.co.uk

Entry 1

Date	2021-10-04
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2022-10-04
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	41
Total items failed	16

MOT #20	2021-10-05 17:04
MOT test number	167340222302
Result	✓ Passed
Next expiry date	2022-10-04

MOT #19	2021-10-05 15:12
MOT test number	274615457252
Result	✗ Failed

- Fail** Offside Front Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.5 (b) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))
- Pass with rectification** Nearside Rear Passenger's seat insecure (6.2.6 (a) (ii))

**MOT #18** 2020-07-20 11:10**MOT test number** 344356292831**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #17** 2019-07-17 13:00**MOT test number** 496098968753**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Lower Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Non obligatory mirror damaged**Advice** Central Rear Registration plate deteriorated but not likely to be misread Faded and wrinkling (0.1 (b))**Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #16** 2018-07-16 12:57**MOT test number** 101070626175**Result** ✓ Passed**Advice** Nearside door mirror cracked

**MOT #15** 2018-07-16 12:57**MOT test number** 356168959705**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside door mirror cracked**MOT #14** 2017-07-10 09:21**MOT test number** 579570677160**Result** ✓ Passed**Advice** Nearside door mirror glass cracked**MOT #13** 2017-07-10 09:21**MOT test number** 347837080204**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside door mirror glass cracked**MOT #12** 2016-07-21 11:19**MOT test number** 702288733015**Result** ✓ Passed**MOT #11** 2016-07-18 09:12**MOT test number** 777016788386**Result** ✗ Failed**Fail** Offside Side repeater not working (1.4.A.2c)

**MOT #10** 2015-07-17 10:00**MOT test number** 659028195135**Result** ✓ Passed**MOT #9** 2014-07-21 09:41**MOT test number** 986752804245**Result** ✓ Passed**Notice** N/s/f door mirror cracked. o/s/f indicator dim.**MOT #8** 2013-07-25 15:24**MOT test number** 246086703237**Result** ✓ Passed**Notice** Rear O/s brake pipe rusty**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s passenger mirror glass**MOT #7** 2013-07-25 13:45**MOT test number** 889766503220**Result** ✗ Failed**Fail** Nearside Front Wheel nut(s) missing (4.2.A.1e)**Notice** Rear O/s brake pipe rusty**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s passenger mirror glass



MOT #6	2012-05-10 09:54
MOT test number	226281132472
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #5	2011-04-12 15:01
MOT test number	255622901118
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	N/s mirror glass cracked
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4**

2011-04-12 11:58

MOT test number

168002201149

Result**✗ Failed****Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Side repeater missing (1.4.A.2b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Notice** N/s mirror glass cracked**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3**

2010-02-04 15:25

MOT test number

371245930035

Result**✓ Passed****Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2**

2010-02-03 12:28

MOT test number

732974730080

Result**✗ Failed****Fail** Nearside Side repeater not working (1.4.A.2c)**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #1	2009-01-21 10:13
MOT test number	191911529002
Result	✓ Passed
<div>Notice</div> Child seat fitted not allowing full inspection of adult belt	



Tax & MOT check

X

Untaxed

Tax expired:
1 October 2021

X

MOT

Expired:
4 October 2022

Tax status	Expired at 1 October 2021
Days left	942 days too late
MOT expiry date	4 October 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-04-06
Last registration	2021-10-05
Complete history	See info



Registration #1	2005-04-06	17 mi
Registration #2	2009-01-21	31.933 mi
Registration #3	2010-02-03	38.656 mi
Registration #4	2010-02-04	38.679 mi
Registration #5	2011-04-12	45.095 mi
Registration #6	2011-04-12	45.095 mi
Registration #7	2012-05-10	50.634 mi
Registration #8	2013-07-25	56.114 mi
Registration #9	2013-07-25	56.114 mi
Registration #10	2014-07-21	60.796 mi
Registration #11	2015-07-17	66.715 mi
Registration #12	2016-07-18	72.213 mi
Registration #13	2016-07-18	72.213 mi
Registration #14	2016-07-18	72.213 mi
Registration #15	2016-07-18	72.213 mi
Registration #16	2016-07-18	72.213 mi
Registration #17	2016-07-18	72.213 mi
Registration #18	2016-07-18	72.213 mi
Registration #19	2016-07-18	72.213 mi
Registration #20	2016-07-18	72.213 mi
Registration #21	2016-07-18	72.213 mi
Registration #22	2016-07-18	72.213 mi
Registration #23	2016-07-18	72.213 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1759 mm
Length	4634 mm
Wheel base	2835 mm
Kerb weight	1918 kg
Max. allowed weight	2450 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	ATM 022879