





report date: 2024-03-29

General information

Make	PEUGEOT
Model	PARTNER
Colour	Blue
Year of manufacture	2015
Gearbox	-

Engine & fuel consumption

Engine capacity	1.560 cc
Fuel type	Diesel
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-03

Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-06-15
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	6
Total items failed	5

MOT #9	2023-06-12 08:05
MOT test number	493852312548
Result	✓ Passed
Next expiry date	2024-06-15
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8	2023-06-12 08:04
MOT test number	560339990679
Result	★ Failed
Pass with rectification	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no
longer prevents the ingress	of dirt (6.1.7 (g) (ii))
Advice Nearside Rear Ty	yre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no
longer prevents the ingress	of dirt (6.1.7 (g) (ii))

MOT #7	2022-06-06 08:57
MOT test number	126030235783
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6 2022-06-06 08:57

MOT test number 666842586788

Result X Failed

Pass with rectification Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Pass with rectification

Front Headlamp aim too low Both front (4.1.2 (a))

MOT #5 2021-06-16 13:28

MOT test number 468635696494

Result \(\sqrt{Passed} \)

MOT #4 2021-06-16 08:57

MOT test number 658310951390

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice TPMS LIGHT ON

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2019-11-25 13:11

MOT test number 532772938808

Result \sqrt{Passed}

MOT #2 2018-12-07 12:15

MOT test number 554831379128

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2018-02-19 17:18

MOT test number 845053252624

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

_	
Owner	hictory
OWITEI	HIISLULY

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
See in this cheek if this i LooLot had different flamber plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NEW
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-04-27
Last registration	2023-06-12
Complete history	See info



Registration #1	2015-04-27	28 mi
Registration #2	2018-02-19	11.695 mi
Registration #3	2018-12-07	15.339 mi
Registration #4	2019-11-25	19.566 mi
Registration #5		11.777 es
Registration #6	2021-06-16	21.793 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Additional information

Number of seats	5
Engine number	JBFR0018442

CarCheck.co.uk page 12/12