





report date: 2024-03-28

#### General information

Make	CITROEN
Model	DS4 HDI DSTYLE
Colour	Silver
Year of manufacture	2013
Top speed	118 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	110 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

### Internet history

#### Entry 1

Date 2021-09-07

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-04
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	10
Total items failed	5

MOT #11	2023-10-16 09:14
MOT test number	977087365916
Result	✓ Passed
Next expiry date	2024-11-04

MOT #10	2023-10-16 09:14
MOT test number	201036326007
Result	<b>★</b> Failed
Pass with rectification sides (4.7.1 (b) (ii))	Registration plate lamp inoperative in the case of a single lamp or all lamps Both

MOT #9		2022-11-03 17:08
MOT test	number	425905981889
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge bald a	and 2mm (5.2.3 (e))
Advice	Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))		
Advice	Advice Emissions to clean to register	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge 2mr	m (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2022-11-03 11:03

**MOT test number** 397434340757

**Result** X Failed

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 225/45/18 (5.2.3 (d) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge bald and 2mm (5.2.3 (e))

**Advice** Emissions to clean to register

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge 2mm (5.2.3 (e))

MOT #7	2021-10-15 08:50
MOT test number	504387623077

MOT #6	2020-10-30 09:50
MOT test number	224084386379

**Result** 
✓ Passed

MOI #5	2019-10-30 10:40

**MOT test number** 188008690123

Result \( \sqrt{Passed} \)

MOT #4 2018-11-05 12:43

**MOT test number** 519027311449

**Result** ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3		2017-10-07 09:14
MOT test number		291088402493
Result		✓ Passed
MOT #2		2016-10-20 08:41
MOT test number		550939335796
Result		✓ Passed
MOT #1		2016-10-20 08:41
MOT test number		841169123647
Result		<b>×</b> Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	4 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner matery		
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively.		EN
*******		
***************************************		
	More info	
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	OK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	Mana infa	
	More info >	

CarCheck.co.uk page 9/12



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-10-31
Last registration	2023-10-16
Complete history	See info



Registration #1	2013-10-31	19 mi
Registration #2	2016-10-20	20.294 mi
Registration #3	2016-10-20	20.294 mi
Registration #4	2017-10-07	29.261 mi
Registration #5	2018-11-05	39.132 mi
Registration #6	2019-10-30	40.823 mi
Registration #7	2020-10-30	41.703 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1805 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBET0001963

CarCheck.co.uk page 12/12