





report date: 2024-03-28

#### General information

Make	MAZDA
Model	2 TAMURA
Colour	Blue
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	83 BHP
Max. torque	121 Nm at 3.500 rpm
Engine capacity	1.349 сс
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



## Internet history


#### Entry 1

Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-02
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #12	2024-02-28 09:08
MOT test number	539910027679
Result	<b>✓</b> Passed
Next expiry date	2025-03-02
Advice Rear suspension beam corroded	
Advice Front Sub-frame corroded but not seriou	usly weakened (5.3.3 (b) (i))
Advice Guards fitted to underside of vehicle and	d outer sills
Advice Brake pipe corroded, covered in grease	or other material all (1.1.11 (c))

MOT #11		2024-02-28 09:07
MOT test	number	715408857089
Result		<b>×</b> Failed
Pass wi	th rectification Headlamp aim too high both front (4.1.2	(a))
Advice	Rear suspension beam corroded	
Advice Brake pipe corroded, covered in grease or other material all (1.1.11 (c))		
Advice Guards fitted to underside of vehicle and outer sills		
Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))		
Pass wi	th rectification Nearside Rear Seat belt buckle not function	oning as intended (7.1.2 (d))

CarCheck.co.uk page 3/12



CV12GOA

report date: 2024-03-28

MOT #10		2023-02-18 08:58
MOT test	number	545293232102
Result		✓ Passed
Advice	Brake pipe corroded, covered in grease or other material All (1.1.11 (c))	
Advice	Rear Beam axle slightly corroded	
Advice	Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Suspension component mounting prescribed area is corroded but not considered excessive Both rear (5.3.6 (a) (i))		

Advice Suspension component mounting prescribed area is corroded but not considered excessive Both rear (5.3.6 (a) (i))	
MOT #9	2022-02-14 16:57
MOT test number	294371448576
Result	<b>√</b> Passed
MOT #8	2021-02-19 11:46
MOT test number	225996369142
Result	<b>✓</b> Passed
MOT #7	2020-03-03 15:17
MOT test number	765757279328
Result	✓ Passed
MOT #6	2019-02-21 17:10
MOT test number	765033482963
Result	<b>✓</b> Passed
MOT #5	2019-02-21 17:10
MOT test number	921298358036

MOT #5		2019-02-21 17:10
MOT test number		921298358036
Result		<b>×</b> Failed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	

CarCheck.co.uk page 4/12



CV12GOA

report date: 2024-03-28

MOT #4	2018-02-10 12:39
MOT test number	478836771537
Result	✓ Passed
MOT #3	2017-02-04 10:28
MOT test number	709151260735
Result	✓ Passed
Advice Flat spots on near side and off side rear tyres	

MOT #2	2016-02-06 10:39
MOT test number	607839378243
Result	<b>✓</b> Passed
MOT #1	2015-02-14 09:12
MOT test number	905845145047
Result	✓ Passed

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	2 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



CV12GOA

report date: 2024-03-28

#### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



furthe scinors

CV12GOA

report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a>. More info > Plate changes See in this check if this MAZDA had different number plates. ober of plates

More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-01
Last registration	2024-02-28
Complete history	See info



Registration #1	2012-03-01	22 mi
Registration #2	2015-02-14	22.383 mi
Registration #3	2016-02-06	29.578 mi
Registration #4	2017-02-04	37.912 mi
Registration #5	2018-02-10	45.682 mi
Registration #6	2019-02-21	53.211 mi
Registration #7	2019-02-21	53.211 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1485 kg

## Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZJ A50824

CarCheck.co.uk page 12/12