





General information

Make FL	IAT
Model PA	ANDA EASY
Colour W	/hite
Year of manufacture 20	014
Top speed 99	9 mph
0 - 60 mph 14	4.2 seconds
Gearbox 5	speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 сс
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	120 g/km
CO2 label	С







Internet history

Entry 2	
Date	2021-06-24
Pictures	19
Listing price	View report



source: yesauto.com


Entry 1	
Date	2021-06-22
Pictures	20
Listing price	View report



source: autotrader.co.uk









MOT history

MOT expiry date	2024-07-06
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	9
Total items failed	10

MOT #13	2023-06-21 13:02
MOT test number	150742296666
Result	✓ Passed
Next expiry date	2024-07-06

MOT #12	2022-06-28 10:05
MOT test number	176648221357
Result	✓ Passed

MOT #11	2022-06-22 12:46	
MOT test number	716697485908	
Result	🗙 Failed	
Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))		
Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))		
Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))		
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive (i))	movement (5.3.4 (a)	

MOT #10	2021-06-24 10:35
MOT test number	136441927870
Result	✓ Passed





МОТ #9		2021-06-17 10:12
MOT tes	t number	672085112877
Result		🗙 Failed
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
MOT #8		2020-07-07 15:55
MOT tes	t number	397961382529
Result		✓ Passed
Advice	Advise both front brake discs corroded and pads wearing low	
MOT #7		2020-07-07 12:16
MOT tes	t number	311103103559
Result		🗙 Failed
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or li	ight sources (4.7.1
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Advise both front brake discs corroded and pads wearing low

MOT #6	2019-06-14 14:55
MOT test number	289680432909
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weaker	ned both (1.1.14 (a) (ii))

MOT #5	2019-06-11 11:55
MOT test number	149611987646
Result	🗙 Failed
AdviceFront Brake disc worn, pitted or scored, but not seriously weakened bFailOil leaking excessively from engine lower sump pan (8.4.1 (a) (i))	ooth (1.1.14 (a) (ii))





MOT #4	2018-06-14 12:23	
MOT test	number 785426752998	
Result	✓ Passed	
Advice	Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #3	2017-06-20 14:45
MOT test number	640233861708
Result	✓ Passed

MOT #2	2016-12-09 11:18
MOT test number	952958369901
Result	✓ Passed

MOT #1	2016-12-06 13:46
MOT test number	923792274582
Result	🗙 Failed
Fail Nearside Headlamp insecure (1.7.3)	
Fail Nearside rear parking (secondary) brake grabbing severely (3.7.B.6b)	
Fail Offside Headlamp aim too high (1.8)	
Fail Offside rear parking (secondary) brake grabbing severely (3.7.B.6b)	



SA14MZY report date: 2024-03-29

Tax & MOT check

✓ Taxed Tax due: 1 June 2024	MOT Expires: 6 July 2024
Tax status	Valid until 1 June
Days left	33
MOT expiry date	6 July 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-03-20
Last registration	2023-06-21
Complete history	See info



Registration #1	2014-03-20	7 mi
Registration #2	2016-12-06	20.466 mi
Registration #3	2016-12-09	20.466 mi
Registration #4	2017-06-20	21.592 mi
Registration #5	2018-06-14	28.198 mi
Registration #6	2019-06-11	29.918 mi
Registration #7	2019-06-14	29.918 mi
Registration #8	2020-07-07	36.431 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight	
Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg
Additional information	
Fuel tank capacity	37
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	0839737