



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D3 SE LUX
Colour	Blue
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 2


Date	2023-03-12
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2022-03-10
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-23
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	27
Total items failed	10

MOT #17	2024-02-29 17:53
MOT test number	384708152664
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back (5.3.4 (a) (i))
Advice	Play in steering rack inner joint(s)
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back (5.3.4 (a) (i))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #16**

2024-02-29 12:26

**MOT test number**

193092475389

**Result**

✗ Failed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back (5.3.4 (a) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back (5.3.4 (a) (i))

**Advice** Play in steering rack inner joint(s)

**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #15**

2023-03-07 14:38

**MOT test number**

258391260154

**Result**

✓ Passed

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Under tray fitted

**MOT #14**

2022-03-24 10:54

**MOT test number**

620262403926

**Result**

✓ Passed

**MOT #13**

2022-03-15 12:48

**MOT test number**

273710959988

**Result**

✗ Failed

**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #12** 2021-07-26 09:58**MOT test number** 551953341372**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #11** 2021-07-26 09:46**MOT test number** 252784572767**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2020-07-15 09:51**MOT test number** 673943962645**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-07-14 09:06**MOT test number** 660348170058**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #8** 2019-07-29 10:10**MOT test number** 844456660490**Result** ✓ Passed

- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing inner tyre wall cracking (5.2.3 (d) (ii))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2018-07-26 14:53**MOT test number** 987267539990**Result** ✓ Passed**MOT #6** 2018-07-26 14:53**MOT test number** 190218096556**Result** ✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))

**MOT #5** 2017-07-24 08:10**MOT test number** 772778015219**Result** ✓ Passed**MOT #4** 2016-07-27 13:06**MOT test number** 926404443059**Result** ✓ Passed

- Advice** Offside brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3	2015-08-10 15:42
MOT test number	178852525267
Result	✓ Passed
MOT #2	2015-08-10 14:06
MOT test number	348552925418
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
MOT #1	2014-08-18 09:16
MOT test number	395090034456
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
23 March 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	23 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-09-29
Current registration	 *****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-09-01
Last registration	2024-02-29
Complete history	<a href="#">See info</a>



Registration #1	2011-09-01	15 mi
Registration #2	2014-08-18	41.506 mi
Registration #3	2015-08-10	55.157 mi
Registration #4	2015-08-10	55.157 mi
Registration #5	2016-07-27	66.021 mi
Registration #6	2017-07-24	74.384 mi
Registration #7	2018-07-26	82.820 mi
Registration #8	2018-07-26	82.820 mi
Registration #9	2019-07-29	88.544 mi
Registration #10	2020-07-14	94.117 mi
Registration #11	2020-07-14	94.117 mi
Registration #12	2020-07-14	94.117 mi
Registration #13	2020-07-14	94.117 mi
Registration #14	2020-07-14	94.117 mi
Registration #15	2020-07-14	94.117 mi
Registration #16	2020-07-14	94.117 mi
Registration #17	2020-07-14	94.117 mi
Registration #18	2020-07-14	94.117 mi
Registration #19	2020-07-14	94.117 mi
Registration #20	2020-07-14	94.117 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1847 mm
Height	1400 mm
Length	4615 mm
Wheel base	2640 mm
Kerb weight	1789 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	1029126