






General information

| Make | FIAT |
|---------------------|----------------|
| Model | PUNTO ACTIVE |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 97 mph |
| 0 - 60 mph | 13.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| D | CO DUD |
|-------------------------|---------------------|
| Power | 68 BHP |
| Max. torque | 102 Nm at 3.000 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 42.2 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 123 g/km |
| CO2 label | D |







Internet history

| Entry 1 | |
|---------------|-------------|
| Date | 2021-06-24 |
| Pictures | 13 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| MOT expiry date | 2025-04-24 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 10 |
| Failed MOT tests | 2 |
| Total advice items | 12 |
| Total items failed | 2 |

| MOT #12 | 2024-04-25 08:37 |
|------------------|------------------|
| MOT test number | 790227176658 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-24 |

| MOT #11 | 2023-02-27 10:16 |
|--------------------------------------|------------------|
| MOT test number | 553325515206 |
| Result | ✓ Passed |
| Advice Exhaust tail box deteriorated | |

| MOT #10 | 2022-01-31 12:03 |
|--|------------------|
| MOT test number | 420218604517 |
| Result | ✓ Passed |
| Advice Exhaust tail box outer skin deteriorating | |

| MOT #9 | 2021-01-25 10:14 |
|-----------------|------------------|
| MOT test number | 453122015773 |
| Result | ✓ Passed |

| MOT #8 | 2019-07-29 15:42 |
|-----------------|------------------|
| MOT test number | 319966335821 |
| Result | ✓ Passed |





| MOT #7 | | 2019-07-29 08:56 |
|----------|---|------------------|
| MOT test | number | 372914222194 |
| Result | | 🗙 Failed |
| Fail Ne | earside Rear Hydraulic brake cylinder leaking hydraulic fluid (1.1.16 (b) (i)) | |
| MOT #6 | | 2018-07-27 13:19 |
| | | |
| MOT test | number | 747862651938 |
| Result | | Passed |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i)) | |
| Advice | Tyre worn close to legal limit/worn on edge nearside front on 2.7mm (5.2.3 (e)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i)) | |

| MOT #5 | | 2017-07-29 07:37 |
|----------|--|------------------|
| MOT test | number | 346402376904 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Rear Direction indicators slightly discoloured (1.4.A.2f) | |
| Advice | Nearside Rear Direction indicators slightly discoloured (1.4.A.2f) | |

| MOT #4 | | 2017-07-29 07:37 |
|---|--|------------------|
| MOT test number | | 736704613643 |
| Result | | 🗙 Failed |
| Advice Nearside Rear Direction | indicators slightly discoloured (1.4.A.2f) | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | | |
| Pass with rectification Winds | creen washer provides insufficient washer liquid (8.2.3) | |
| Advice Offside Rear Direction in | ndicators slightly discoloured (1.4.A.2f) | |





| MOT #3 | 2016-07-27 09:05 |
|--|-----------------------------|
| MOT test number | 887925578753 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2015-10-15 11:50 |
| MOT test number | 125667610415 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2014-10-16 08:57 |
| MOT test number | 638379984247 |
| Result | ✓ Passed |
| Advice Parking brake: parking brake efficiency only just met. It would apper requires adjustment or repair. (3.7.B.7) | ear that the braking system |



Tax & MOT check

| √ Taxed | √ MOT |
|--------------------------------|----------------------------------|
| Tax due: 1 July 2024 | Expires: 24 April 2025 |
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 24 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Dumage 2 | E E E E |
| Date | J. |
| Category | amer |
| Туре | |

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ************ | |
|--|-------------|
| ******* | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| | |
| Number of plates | , |
| Number of plates Carnet registration | |
| Number of plates Correct registration Plate since | |
| Number of plates Correct registration Plate since Correct registration | |
| Number of plates Current registration Plate since Current registration Plate since | 8000-20-20 |





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 14 |
| First mileage registration | 2011-10-18 |
| Last registration | 2024-04-25 |
| Complete history | <u>See info</u> |



| Registration #1 | 2011-10-18 | 17 mi |
|---|------------|--|
| Registration #2 | 2014-10-16 | 14.652 mi |
| Registration #3 | 2015-10-15 | 18.390 mi |
| Registration #4 | 2016-07-27 | 21.608 mi |
| Registration #5 | 2017-07-29 | 30.254 mi |
| Registration #6 | 2017-07-29 | 30.254 mi |
| Registration #7 | 2018-07-27 | 38.235 mi |
| | | |
| Registration #8 | | 11.777 mil |
| Registration #8 Registration #9 | | 11.777 es |
| - | | 11.227 es |
| Registration #9 | | 11.227 es 11.227 es 11.227 es 11.227 es |
| Registration #9 Registration #10 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #9 Registration #10 Registration #11 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1687 mm |
| Height | 1490 mm |
| Length | 4065 mm |
| Wheel base | 2510 mm |
| Kerb weight | 1030 kg |
| Max. allowed weight | 1590 kg |
| Additional information | |
| Fuel tank capacity | 45 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | 6290534 |