



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Beige
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 2

Date	2022-01-14
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-12-09
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-08
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	19
Total items failed	7

MOT #19	2023-12-07 15:12
MOT test number	545052512126
Result	✓ Passed
Next expiry date	2024-12-08

MOT #18	2022-12-02 14:30
MOT test number	641650645717
Result	✓ Passed

MOT #17	2022-12-02 14:30
MOT test number	922274046688
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #16	2021-12-09 12:20
MOT test number	265313474470
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Tyre slightly damaged/cracking or perishing Both front (5.2.3 (d) (ii))

**MOT #15** 2021-04-06 13:55**MOT test number** 165343019455**Result** ✓ Passed**Advice** Front tyres perrished**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2021-04-05 12:51**MOT test number** 138517471430**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front tyres perrished**MOT #13** 2020-03-24 15:02**MOT test number** 899847168415**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Exhaust system centre and rear corroded hangers may break soon**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 2155516 (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2019-04-03 11:58**MOT test number** 760974683956**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11** 2018-03-05 15:43**MOT test number** 300929841523**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2018-03-05 15:43**MOT test number** 161483615241**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**MOT #9** 2017-03-01 16:01**MOT test number** 584650609872**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #8** 2016-03-03 11:55**MOT test number** 496096859338**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2015-02-25 14:47**MOT test number** 977456055055**Result** ✓ Passed

**MOT #6** 2015-02-25 12:08**MOT test number** 376886755029**Result** ✗ Failed**Fail** Fuel cap/sealing device missing (7.2.4a)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #5** 2014-02-02 10:38**MOT test number** 846663034055**Result** ✓ Passed**MOT #4** 2012-12-13 15:06**MOT test number** 885478142359**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-12-22 10:25**MOT test number** 885326451374**Result** ✓ Passed**MOT #2** 2010-12-17 08:49**MOT test number** 364571050348**Result** ✓ Passed



MOT #1 2010-12-15 12:16

MOT test number 264819140317

Result ✗ Failed

**Notice** Offside mirror glass cracked

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
8 December 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	8 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	2015-01-01
Owner 2	2015-01-01
Owner 3	2015-01-01
Owner 4	2015-01-01
Owner 5	2015-01-01
Owner 6	2015-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	FH57YTV
Plate since	2015-01-01
Current registration	FH57YTV
Plate since	2015-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-12-27
Last registration	2023-12-07
Complete history	<a href="#">See info</a>



Registration #1	2007-12-27	13 mi
Registration #2	2010-12-15	16.420 mi
Registration #3	2010-12-17	16.449 mi
Registration #4	2011-12-22	20.540 mi
Registration #5	2012-12-13	24.735 mi
Registration #6	2014-02-02	29.275 mi
Registration #7	2015-02-25	34.735 mi
Registration #8	2015-02-25	34.735 mi
Registration #9	2016-03-03	39.601 mi
Registration #10	2017-03-01	44.767 mi
Registration #11	2018-03-05	48.111 mi
Registration #12	2019-03-05	51.555 mi
Registration #13	2020-03-05	55.000 mi
Registration #14	2021-03-05	58.445 mi
Registration #15	2022-03-05	61.890 mi
Registration #16	2023-03-05	65.335 mi
Registration #17	2024-03-05	68.780 mi
Registration #18	2025-03-05	72.225 mi
Registration #19	2026-03-05	75.670 mi
Registration #20	2027-03-05	79.115 mi
Registration #21	2028-03-05	82.560 mi
Registration #22	2029-03-05	86.005 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118