





report date: 2024-03-28

## General information

Make	BMW
Model	525 525D SE
Colour	Blue
Year of manufacture	2002
Top speed	136 mph
0 - 60 mph	9.1 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	161 BHP	
Max. torque	350 Nm at 2.000 rpm	
Engine capacity	2.497 cc	
Cylinders	6	
Fuel type	Diesel	
Consumption city	25.5 mpg	
Consumption extra urban	44.1 mpg	
Consumption combined	34.9 mpg	
CO2 emission	216 g/km	
CO2 label	K	



CarCheck.co.uk page 1/16



# Internet history

## Entry 1

Date 2021-01-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/16



# MOT history

MOT expiry date	2022-08-17
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	54
Total items failed	14

MOT #23		2021-08-03 08:52
MOT test	number	889209084415
Result		✓ Passed
Next expiry date 2022-08-17		2022-08-17
Advice (a) (i))  Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1		
<b>Advice</b> (7.1.1 (a)	Nearside Rear Seat belt anchorage prescribed area is corroded but not c	considered excessive

MOT #22		2020-08-18 17:55
MOT test	number	701242616359
Result		✓ Passed
Advice	Offside Front Play in steering rack inner joint(s)	
Advice	Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice seriously a	Advice Offside Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))	
Advice	Nearside Front Play in steering rack inner joint(s)	
Advice	Central Rear Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/16



Result

DK52LNJ report date: 2024-03-28

Passed

**MOT #21** 2019-09-26 10:24

MOT test number 638735844969

Advice Central Rear Oil leak, but not excessive Diff plug seal (8.4.1 (a) (i))

**MOT #20** 2018-09-19 13:09

**MOT test number** 145424465599

**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Engine cover, under-trays and sill covers fitted

**Advice** Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

**MOT #19** 2018-09-19 10:32

**MOT test number** 574881993642

**Result** X Failed

**Advice** Engine cover, under-trays and sill covers fitted

**Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

**MOT #18** 2017-09-27 14:50

MOT test number 351788390123

Result 

Passed

Advice Fuel Pipe/s corroded

**Advice** Vehicle structure has slight corrosion (6.1.A.1)

CarCheck.co.uk page 4/16



**MOT #17** 2017-09-27 09:54 **MOT test number** 535298339807 Result × Failed Fail Offside rear parking brake recording little or no effort (3.7.B.6a) Fuel Pipe/s corroded **Advice** Fail Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2) Fail Nearside rear parking brake recording little or no effort (3.7.B.6a) **Advice** Vehicle structure has slight corrosion (6.1.A.1) Fail Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2) Parking brake: efficiency below requirements (3.7.B.7) Fail

MOT #16		2016-09-28 11:54
MOT test	number	814987677014
Result		✓ Passed
Advice	Handbrake as a low reading of 17%	
Advice	Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Fuel Pipe/s corroded	
Advice	Engine cover, under-trays and sill covers fitted	
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice	Vehicle structure has slight corrosion (6.1.A.1)	

CarCheck.co.uk page 5/16



MOT test number

Result

Advice Vehicle structure has slight corrosion (6.1.A.1)

Advice Engine cover and under trays fitted

Advice Handbrake reading 16%

MOT test number
961294885080

Result

Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

Advice Engine cover and under trays fitted

Advice Vehicle structure has slight corrosion (6.1.A.1)

Advice Handbrake reading 16%

MOT test number

S27456964222

Result

Notice Under-trays fitted obscuring some underside components

Notice Fuel pipe/s corroded

Notice Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 6/16



**MOT #12** 2014-09-23 10:42 **MOT** test number 987576264219 Result × Failed Fail Offside rear parking brake recording little or no effort (3.7.B.6a) Notice Fuel pipe/s corroded **Notice** Under-trays fitted obscuring some underside components Nearside rear parking brake recording little or no effort (3.7.B.6a) Fail **Notice** Spare tyre defective Fail Parking brake: efficiency below requirements (3.7.B.7) **Notice** Prop-shaft flange bolt(s) loose/missing **Notice** Tool tray in boot lid insecure

MOT #11

MOT test number

735646863291

Result

Advice

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

918576863252

Result

Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

CarCheck.co.uk page 7/16



MOT test number
916629962264

Result
Notice Fuel pipe/s corroded
Notice Items removed from driver's view prior to test

MOT test number

857729762218

Result

Fail Offside Rear position lamp(s) not working (1.1.A.3b)

Notice Items removed from driver's view prior to test

Notice Fuel pipe/s corroded

Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)

 MOT #7
 2011-09-14 15:53

 MOT test number
 876717551252

 Result
 ✓ Passed

 MOT #6
 2011-09-14 14:35

 MOT test number
 498437351224

 Result
 X Failed

 Fail
 Brake pipe excessively corroded (3.6.B.2c)

CarCheck.co.uk page 8/16



**MOT #5** 2010-09-13 09:40 310226750295 **MOT** test number Result ✓ Passed **Notice** Front tyres wearing on inner and outter edges **Advice** Power steering component(s) has slight seepage from a component (2.3.3b) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Front Exhaust has a minor leak of exhaust gases (7.1.2) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4

MOT test number

Result

MOT #3

2009-09-23 09:47

341266469489

√ Passed

MOT test number 520365258248

Result ✓ Passed

MOT #2

MOT test number

252189967216

Result

Notice Engine undertray fitted

Notice Both rear tyre treads low on inner shoulders +cracking around circumferences

MOT #1 2006-09-29 15:36

MOT test number 603592476253

Result ✓ Passed

CarCheck.co.uk page 9/16





### Tax & MOT check



X MOT

Tax expired: 1 March 2023

Expired: 17 August 2022

Tax status Expired at 1 March 2023

Days left 424 days too late

MOT expiry date 17 August 2022

Full MOT history See MOT history

### Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 10/16



### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 12/16



Owner	history
OWITCE	iliotoi y

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I	
manage of the same	
********	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK NEZ
Plate since	
	More info >

CarCheck.co.uk page 13/16



### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 14/16



# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2002-10-11
Last registration	2021-08-03
Complete history	See info



Registration #1	2002-10-11	11 mi
Registration #2	2006-09-29	31.191 mi
Registration #3	2007-09-26	38.749 mi
Registration #4	2008-09-11	46.516 mi
Registration #5	2009-09-23	53.957 mi
Registration #6	2010-09-13	59.978 mi
Registration #7	2011-09-14	63.180 mi
Registration #8	2011-09-14	63.180 mi
Registration #9	2012-09-25	67.535 mi
Registration #10	2012-09-25	67.535 mi
Registration #11	2013-09-23	71.388 mi
Registration #12	2013-09-23	71.388 mi
Registration #13	2014-09-23	74.888 mi
Registration #14		77,777 46
Registration #15		77,777 46
Registration #16		71.777 es
Registration #17		11.177 es
Registration #18		11.177 es
Registration #19		11.177 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 46
Registration #23		11.777 mi
Registration #24		



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1800 mm
Height	1435 mm
Length	4775 mm
Wheel base	1558 mm

## Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	21829964

CarCheck.co.uk page 16/16