



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V I-VTEC ES
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	174 Nm at 4.300 rpm
Engine capacity	1.799 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-11-11
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-11-10
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-02
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	21
Total items failed	13

MOT #182024-04-03 11:16

MOT test number822318068967

Result✓ Passed

Next expiry date2025-04-02

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #172024-04-03 11:16

MOT test number596917022333

Result✗ Failed

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #162023-01-27 16:08

MOT test number573185415393

Result✓ Passed

**MOT #15** 2022-12-05 11:16**MOT test number** 405593163699**Result** ✗ Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Rear Tyre obviously under inflated (5.2.3 (l))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #14 2021-12-08 16:40**MOT test number** 579171437154**Result** ✓ Passed**MOT #13** 2021-11-11 13:02**MOT test number** 466127044390**Result** ✗ Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Service brake excessively binding (1.2.1 (f))

MOT #12 2020-10-27 15:31**MOT test number** 999941253027**Result** ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2020-10-27 12:04**MOT test number** 916639391681**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #10** 2019-10-24 11:01**MOT test number** 524511229683**Result** ✓ Passed**MOT #9** 2018-10-30 16:02**MOT test number** 562457372197**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8** 2018-10-29 13:12**MOT test number** 482275205052**Result** ✗ Failed**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**MOT #7** 2017-10-30 13:37**MOT test number** 436172775905**Result** ✓ Passed**MOT #6** 2016-10-31 16:42**MOT test number** 205758049572**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Front tyres worn badly on both inner and outer edges.**MOT #5** 2016-10-31 10:47**MOT test number** 830317305608**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Front tyres worn badly on both inner and outer edges.**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2015-10-26 11:15**MOT test number** 133490215958**Result** ✓ Passed**MOT #3** 2014-10-30 11:17**MOT test number** 296323004373**Result** ✓ Passed**MOT #2** 2013-10-30 15:28**MOT test number** 897273003357**Result** ✓ Passed



MOT #1	2012-11-01 11:58
MOT test number	949146802340
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
2 April 2025

Tax status	Valid until 1 December
Days left	215
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	FE59ENX
Plate since	2019-09-29
Current registration	FE59ENX
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-10-30
Last registration	2024-04-03
Complete history	See info



Registration #1	2009-10-30	28 mi
Registration #2	2012-11-01	22.122 mi
Registration #3	2013-10-30	31.151 mi
Registration #4	2014-10-30	39.359 mi
Registration #5	2015-10-26	48.686 mi
Registration #6	2016-10-31	58.516 mi
Registration #7	2016-10-31	58.526 mi
Registration #8	2017-10-30	67.679 mi
Registration #9	2018-10-29	79.711 mi
Registration #10	2018-10-30	79.735 mi
Registration #11	2019-10-24	87.520 mi
Registration #12	2020-10-29	95.305 mi
Registration #13	2021-10-29	103.090 mi
Registration #14	2022-10-29	110.875 mi
Registration #15	2023-10-29	118.660 mi
Registration #16	2024-04-03	126.445 mi
Registration #17		
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1423 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	R18A13301962