




report date: 2024-03-28

General information

Make	MINI
Model	PACEMAN COOPER
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 3

Date 2023-01-05

Pictures 21

Listing price [View report](#)




source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date 2023-01-03

Pictures 20

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-09-02

Pictures 12

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-01-04
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #9	2023-01-05 13:13
MOT test number	798410221055
Result	✓ Passed
Next expiry date	2024-01-04

MOT #8	2022-11-01 16:15
MOT test number	429318259269
Result	✓ Passed

MOT #7	2021-11-01 15:18
MOT test number	301447424195
Result	✓ Passed

MOT #6	2021-08-20 09:01
MOT test number	194774618517
Result	✓ Passed

- Minor** Windscreen wiper blade defective both front (3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2020-08-20 11:04**MOT test number** 110629215430**Result** ✓ Passed**Advice** Nearside front tyre worn low**MOT #4** 2020-08-20 11:04**MOT test number** 321921782489**Result** ✗ Failed**Pass with rectification** Nearside Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**Advice** Nearside front tyre worn low**MOT #3** 2019-07-26 15:02**MOT test number** 299531742455**Result** ✓ Passed**Advice** Offside front wiper smearing**Advice** Sticker on nearside front of windscreen**MOT #2** 2018-07-16 15:22**MOT test number** 347774010713**Result** ✓ Passed**MOT #1** 2017-05-02 08:36**MOT test number** 321410664337**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✗
MOT

Expired:
4 January 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	4 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-29
Last registration	2023-01-05
Complete history	See info



Registration #1	2014-05-29	7 mi
Registration #2	2017-05-02	36.279 mi
Registration #3	2018-07-16	45.202 mi
Registration #4	2019-07-26	51.217 mi
Registration #5	2020-08-20	55.893 mi
Registration #6	2020-08-20	55.893 mi
Registration #7	2021-08-20	69.132 mi
Registration #8	2022-01-05	69.132 mi
Registration #9	2022-01-05	69.132 mi
Registration #10	2022-01-05	69.132 mi
Registration #11	2022-01-05	69.132 mi
Registration #12	2022-01-05	69.132 mi
Registration #13	2022-01-05	69.132 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A712J684