





report date: 2024-03-28

General information

Make	MAZDA
Model	RX-8 RX-8 231PS
Colour	Red
Year of manufacture	2006
Top speed	146 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	237 BHP
Max. torque	216 Nm at 6.000 rpm
Engine capacity	2.616 cc
Cylinders	2
Fuel type	Petrol
Consumption city	17.9 mpg
Consumption extra urban	31.7 mpg
Consumption combined	24.8 mpg
CO2 emission	284 g/km
CO2 label	М



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-11-03

Pictures 1



source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2021-12-15
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	8
Total items failed	10

MOT #17	2020-12-16 10:42
MOT test number	579019116706
Result	✓ Passed
Next expiry date	2021-12-15
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2019-06-15 09:55
MOT test number	496996953439
Result	✓ Passed

MOT #	15	2019-06-05 11:07
MOT te	st number	949631018580
Result		× Failed
Fail	Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))	
Fail	Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2	(b))
Fail	Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #14

MOT test number

446670607332

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13 2018-06-05 15:04 **MOT** test number 202369340425 Result **X** Failed Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) Exhaust has a major leak of exhaust gases rear silencer (6.1.2 (a)) Fail Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2017-06-06 11:08
MOT test number	995374060676
Result	✓ Passed
MOT #11	2016-04-20 10:14
MOT test number	598297426769
Result	✓ Passed
MOT #10	2015-04-17 10:35
MOT test number	816007005120
Result	✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9		2015-04-17 10:35
MOT test number		627337805184
Result		× Failed
Pass with rectification	Nearside Rear coil spring broken (2.4.C.1a)	

MOT #8	2014-05-12 15:00
MOT test number	989982434190
Result	✓ Passed
MOT #7	2013-05-02 15:36
MOT test number	279112023403
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #6		2012-05-03 12:27
MOT test number		547404722171
Result		✓ Passed
MOT #5		2011-04-06 16:48
MOT test number		335356491045
Result		✓ Passed
MOT #4		2011-04-06 16:48
MOT test number		108456991092
Result		X Failed
Pass with rectification	Offside Front Anti-roll bar linkage missing (2.4.G.1)	

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3

MOT test number

134046090458

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

 MOT #2
 2009-03-20 11:07

 MOT test number
 524509679069

 Result
 ✓ Passed

 MOT #1
 2009-03-20 11:07

 MOT test number
 194639679071

 Result
 X Failed

Pass with rectification Front Headlamp aim too high (1.8)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax expired: 2 November 2021

X MOT

Expired: 15 December 2021

Tax status	Expired at 2 November 2021
Days left	908 days too late
MOT expiry date	15 December 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



furthe scinors

MV06FPK

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MAZDA had different number plates.

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-03-31
Last registration	2020-12-16
Complete history	See info



Registration #1	2006-03-31	11 mi
Registration #2	2009-03-20	20.787 mi
Registration #3	2010-04-06	29.936 mi
Registration #4	2011-04-06	38.539 mi
Registration #5	2012-05-03	47.436 mi
Registration #6	2013-05-02	54.636 mi
Registration #7	2014-05-12	62.555 mi
Registration #8	2015-04-17	69.570 mi
Registration #9		11.177 es
Registration #10		11.117 es
Registration #11		11.177 es
Registration #12		11.117 es
Registration #13		11.177 es
Registration #14		11.177 es
Registration #15		11.177 es

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 12/13



MV06FPK report date: 2024-03-28

Dimensions & weight

Width	1770 mm
Height	1340 mm
Length	4425 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	61
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	13B 487479

CarCheck.co.uk page 13/13