





report date: 2024-03-29

General information

Make	MERCEDES
Model	C C180K SE
Colour	Silver
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	220 Nm at 2.500 rpm
Engine capacity	1.796 сс
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-29

MOT history

MOT expiry date	2020-10-03
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	23
Total items failed	15

MOT #12		2019-04-04 13:20
MOT test	number	612980215712
Result		✓ Passed
Next expi	ry date	2020-10-03
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))

MOT #11	2019-03-28 16:12
MOT test number	853804133939
Result	× Failed
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1	11 (c))
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.	11 (c))
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.1	11 (c))
Fail Offside Side repeater not working (4.4.1 (a) (ii))	
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.3	1.11 (c))

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT #10

MOT test number

878801365767

Result

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nsf tyre scubbing on the inner edge

MOT #9 2018-03-27 11:00 **MOT** test number 958380626371 Result **X** Failed Offside Front Brake pipe slightly corroded (3.6.B.2c) **Advice** Fail Nearside Front coil spring broken (2.4.C.1a) Advice Nsf tyre scubbing on the inner edge Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Nearside Front Side repeater not working wing mirror (1.4.A.2c) Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c) Central Exhaust system not adequately supported both hangers (7.1.1) Fail Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #8		2016-08-24 15:57
MOT test	number	336653592761
Result		✓ Passed
Advice	Wear starting to affect nearside front suspension arm ball joint	
Advice Wear starting to affect offside front suspension lower arm ball joint		
Advice	Brake pipe slightly corroded front to rear (3.6.B.2c)	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number
985846621465

Result

Advice Brake pipe slightly corroded front to rear (3.6.B.2c)

Advice Wear starting to affect offside front suspension lower arm ball joint

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Wear starting to affect nearside front suspension arm ball joint

MOT #6

MOT test number

636588495091

Result

V Passed

Notice Exhaust corroded rear of centre cat/silencer

MOT #5 2015-03-26 14:57 957225185093 **MOT** test number Result × Failed Offside Track rod end ball joint has excessive play (2.2.B.1f) Fail **Notice** Exhaust corroded rear of centre cat/silencer Fail Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2) Nearside Track rod end ball joint has excessive play (2.2.B.1f) Fail Fail Offside Front coil spring broken (2.4.C.1a) Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #4

MOT test number

478587454026

Result

Notice Nail in nearside rear tyre

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2012-10-02 09:10

MOT test number 366476672403

Result ✓ Passed

MOT #2 2011-09-30 15:10

MOT test number 685143771253

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2010-10-01 14:42

MOT test number 613004070223

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax expired: 18 February 2021

X MOT

Expired: 3 October 2020

Tax status	Expired at 18 February 2021
Days left	1167 days too late
MOT expiry date	3 October 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Date 2

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2007-11-13
Last registration	2019-04-04
Complete history	See info



Registration #1	2007-11-13	9 mi
Registration #2	2010-10-01	14.784 mi
Registration #3	2011-09-30	25.070 mi
Registration #4	2012-10-02	35.739 mi
Registration #5	2014-02-26	44.435 mi
Registration #6	2015-03-26	52.217 mi
Registration #7	2015-04-08	52.265 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		0.074

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

г.		_		
llim	ensior	יכ אי	WAIC	1nt
		IS CX	WEIL	41 I C

Width	1957 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	1465 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	27194630876940

CarCheck.co.uk page 12/12