





report date: 2024-03-28

General information

| Make | BMW |
|---------------------|-------------------|
| Model | 430 430D M SPORT |
| Colour | Blue |
| Year of manufacture | 2017 |
| Top speed | 155 mph |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 255 BHP |
|-------------------------|---------------------|
| Max. torque | 560 Nm at 2.000 rpm |
| Engine capacity | 2.993 сс |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 134 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/11



Internet history

Entry 6

Date 2022-11-14
Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 5

Date 2022-01-25

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 4

Date 2022-01-06

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

| Date | 2021-10-02 | |
|---------------|--------------------|--|
| Pictures | 10 | |
| Listing price | <u>View report</u> | |

CarCheck.co.uk page 2/11









source: autoonline.co.uk

Entry 2

| Date | 2021-09-11 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

Entry 1

| Date | 2021-09-11 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk



| MOT history | M | OT | history |
|-------------|---|----|---------|
|-------------|---|----|---------|

| MOT expiry date | 2025-02-14 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 16 |
| Total items failed | 0 |

| MOT #8 | 2024-02-09 15:54 |
|------------------|------------------|
| MOT test number | 131526687412 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-14 |

| MOT #7 | 2023-02-15 12:06 |
|-----------------|------------------|
| MOT test number | 874198228788 |
| Result | ✓ Passed |

| MOT #6 | 2022-10-05 09:22 |
|-----------------|------------------|
| MOT test number | 228101812412 |
| Result | ✓ Passed |

| MOT #5 | 2022-09-30 15:29 |
|--------|------------------|
|--------|------------------|

MOT test number 670820180741

Result X Failed

DANGEROUS Offside Rear Tyre has a lump, caused by separation or partial failure of its structure 255/30/20 (5.2.3 (d) (ii))

| MOT #4 | 2021-10-13 15:23 |
|-----------------|------------------|
| MOT test number | 745162756227 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT #3 2021-02-06 13:13 **MOT test number** 202722586646 Result ✓ Passed **Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Slight surface corrosion on rear brake discs Advice Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Both rear tyres close to wear markers **Advice**

| MOT #2 | | 2021-02-05 10:52 |
|----------|------------------------------------------------------------------------------------|------------------|
| MOT test | number | 789033822345 |
| Result | | × Failed |
| MAJOR | Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i | i)) |
| Advice | Slight surface corrosion on rear brake discs | |
| MAJOR | Front Service brake excessively fluctuating (1.2.1 (e)) | |
| Advice | Rear Service brake fluctuating, but not excessively (1.2.1 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Both rear tyres close to wear markers | |

| MOT #1 | 2020-02-08 09:35 |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| MOT test number | 184161588044 |
| Result | ✓ Passed |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 4/11





Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 277 |
| MOT expiry date | 14 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|-----------------------------------------|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



| ^ | |
|-------|----------|
| Owner | hictory |
| OWILL | IIISCUIV |

| e mier metery | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report | |
| | |
| | |
| *************************************** | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this BMW had different number plates. | |
| Number of plates | |
| Current registration | IIK SIE |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2017-02-16 |
| Last registration | 2024-02-09 |
| Complete history | See info |



| Registration #1 | 2017-02-16 | 12 mi |
|-----------------------------------|------------|-----------|
| Registration #2 | 2020-02-08 | 24.919 mi |
| Registration #3 | 2021-02-05 | 30.193 mi |
| Registration #4 | 2021-02-06 | 30.196 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.177 es |
| Registration #7 | | 11.777 es |
| Registration #8 | 2021-10-13 | 34.951 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.177 es |
| Registration #11 | | 11.177 es |
| Registration #12 | | |
| | | |
| Registration #13 | | 11.777 mi |
| Registration #13 Registration #14 | | 11.777 mi |

More info >

CarCheck.co.uk page 10/11




Car features

| S0225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 86% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1825 mm |
|---------------------|---------|
| Height | 1377 mm |
| Length | 4638 mm |
| Wheel base | 2810 mm |
| Kerb weight | 1540 kg |
| Max. allowed weight | 2060 kg |

Additional information

| Fuel tank capacity | 57 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats CarCheck.co.uk | 4 page 11/11 |

Number of axles 2

Engine number 55369889