



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 SW SV
Colour	Grey
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	190 Nm at 4.100 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.0 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-03
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT #21	2022-08-22 11:24
MOT test number	579163808975
Result	✓ Passed
Next expiry date	2023-08-21
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides. (1.1.14 (a) (ii))
Advice	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides. (5.3.4 (a) (i))
Advice	Under tray and engine cover fitted.

MOT #20	2021-08-02 15:16
MOT test number	963741390095
Result	✓ Passed

MOT #19	2021-07-19 09:09
MOT test number	163207514199
Result	✗ Failed
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
MAJOR	Nearside Front Lower Steering linkage ball joint has excessive play (2.1.3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 215/55/17 (5.2.3 (e))
MAJOR	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #18**

2020-07-21 07:48

**MOT test number**

831382174258

**Result**

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Lower Steering linkage ball joint has slight play (2.1.3 (b) (i))

**MOT #17**

2019-07-15 09:15

**MOT test number**

345464013105

**Result**

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Engine mount bush cracking. Under bonnet
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16**

2018-07-10 11:12

**MOT test number**

934431466505

**Result**

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15**

2017-08-04 13:42

**MOT test number**

842641162284

**Result**

✓ Passed

**MOT #14** 2017-07-26 12:00**MOT test number** 873044357265**Result** ✗ Failed

- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**MOT #13** 2016-07-20 13:24**MOT test number** 237578847621**Result** ✓ Passed

- Advice** Offside Front tyre scrubbing on edges of tread. 215/55/17
- Advice** Offside Rear tyre scrubbing on inner tread and cracking around walls and tread.
- Advice** Nearside Rear Tyre worn close to the legal limit scrubbing on inner tread and cracking around tread and walls. (4.1.E.1)
- Advice** Nearside Front tyre scrubbing on edges of tread and has had a outer side wall repair.

**MOT #12** 2015-07-22 12:18**MOT test number** 506273405206**Result** ✓ Passed

- Notice** Offside rear tyre starting to go out of shape and cracking.215/55/17
- Notice** Nearside rear tyre going out of shape and cracking, no cords or ply showing yet.Also has a nail in tread.

**MOT #11** 2015-05-06 16:36**MOT test number** 419486425104**Result** ✓ Passed

- Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)
- Notice** Nearside rear tyre cracking around tread and walls,no cords or ply showing yet. Also has nail in tread.
- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Notice** Offside rear tyre cracking around tread and walls. 215/55/17

**MOT #10**

2015-05-06 12:21

**MOT test number**

788386825122

**Result****✗ Failed****Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Nearside rear tyre cracking around tread and walls, no cords or ply showing yet. Also has nail in tread.**Fail** Offside Front Lower Ball joint has excessive play (2.2.B.1f)**Fail** Offside rear brake binding (3.7.B.1)**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Notice** Offside rear tyre cracking around tread and walls. 215/55/17**MOT #9**

2014-05-03 08:48

**MOT test number**

316923724140

**Result****✓ Passed****MOT #8**

2014-05-02 16:08

**MOT test number**

498532924154

**Result****✗ Failed****Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #7**

2013-01-23 10:24

**MOT test number**

406123923057

**Result****✓ Passed**

**MOT #6** 2012-01-19 08:52**MOT test number** 558509412018**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2011-01-20 11:12**MOT test number** 239750621018**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2011-01-19 16:25**MOT test number** 449839211030**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2010-01-19 14:43**MOT test number** 483699310081**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2010-01-19 10:40
MOT test number	541219710093
Result	✗ Failed
Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2009-01-03 10:07
MOT test number	881683209029
Result	✓ Passed





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-01-20
Last registration	2022-08-22
Complete history	<a href="#">See info</a>



Registration #1	2006-01-20	24 mi
Registration #2	2009-01-03	39.655 mi
Registration #3	2010-01-19	51.455 mi
Registration #4	2010-01-19	51.455 mi
Registration #5	2011-01-19	61.704 mi
Registration #6	2011-01-20	61.704 mi
Registration #7	2012-01-19	71.691 mi
Registration #8	2013-01-23	80.432 mi
Registration #9	2014-05-02	86.779 mi
Registration #10	2014-05-03	86.779 mi
Registration #11	2015-05-06	89.337 mi
Registration #12	2015-05-06	89.337 mi
Registration #13	2016-05-06	91.337 mi
Registration #14	2016-05-06	91.337 mi
Registration #15	2016-05-06	91.337 mi
Registration #16	2016-05-06	91.337 mi
Registration #17	2016-05-06	91.337 mi
Registration #18	2016-05-06	91.337 mi
Registration #19	2016-05-06	91.337 mi
Registration #20	2016-05-06	91.337 mi
Registration #21	2016-05-06	91.337 mi
Registration #22	2016-05-06	91.337 mi
Registration #23	2016-05-06	91.337 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1471 mm
Length	4763 mm
Wheel base	2725 mm
Kerb weight	1545 kg
Max. allowed weight	2105 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	LH2W1350840