





report date: 2024-03-29

General information

Make	FIAT
Model	TIPO LOUNGE
Colour	Grey
Year of manufacture	2017
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Emter.	1
Entry	т.

ciitiy 1	
Date	2021-09-08
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-09
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	23
Total items failed	0

MOT #6		2023-10-10 16:39
MOT test	number	329700038857
Result		✓ Passed
Next expi	ry date	2024-10-09
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened N/S+O,	/S (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened N/S+O/	S (1.1.14 (a) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Nail in tyre	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5 2023-10-09 10:30 146117860055 **MOT** test number Result × Failed **MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened N/S+O/S (1.1.14 (a) (ii)) Advice Nearside Front Nail in tyre Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Rear Shock absorbers has a serious fluid leak N/S+O/S (5.3.2 (b)) MAJOR Advice Rear Brake disc worn, pitted or scored, but not seriously weakened N/S+O/S (1.1.14 (a) (ii)) **Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2022-09-16 10:10 **MOT** test number 122947761724 Result Passed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) **Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #3	2021-09-30 11:15
MOT test number	912485196371
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1

MOT test number

167735123199

Result

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	9 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

\sim	
Owner	nictory
CVVIICI	IIISLUIV
~	,

o mici miscory	
For how long did the current and previous owner(s) have this FIAT? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK NE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0111.5	

Contact info

More info >

CarCheck.co.uk page 10/12



MI	leage	cho	$c \nu$
	ıcauc	CHE	\sim

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-05-19
Last registration	2023-10-10
Complete history	See info



Registration #1	2017-05-19	18 mi
Registration #2	2020-11-11	41.956 mi
Registration #3		11.777 es
Registration #4	2021-09-30	48.472 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1270 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles2Engine number4117117