





report date: 2024-03-28

General information

Make	BMW
Model	3 SERIES 335D XDRIVE M SPORT
Colour	Grey
Year of manufacture	2015
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	308 BHP
Max. torque	630 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-07-10

Pictures 22

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date	2021-06-04
Pictures	0
Listing price	View report

source: yesauto.com

CarCheck.co.uk page 2/11



MOT histo

Fail

MOT expiry date	2024-06-23
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	4
Total items failed	4

MOT #9	2023-06-24 08:34
MOT test number	224679901570
Result	✓ Passed
Next expiry date	2024-06-23

MOT #8	2022-05-31 16:27
MOT test number	358697420008
Result	✓ Passed

MOT #7	2021-06-11 11:53
MOT test number	141916757939
Result	✓ Passed

MOT #6	2021-06-09 19:45

MOT test number 641594050699

Result X Failed

Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



× Failed

MOT #5 2020-09-15 15:32

MOT test number 355600717909

Result \rightarrow Passed

Advice

Offside Rear Tyre slightly damaged/cracking or perishing 255/35/19 (5.2.3 (d) (ii))

MOT #4 2020-09-15 08:55

MOT test number 824805751514

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge 225/40/19 (5.2.3 (e))

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure 225/40/19 (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing 255/35/19 (5.2.3 (d) (ii))

MOT #3 2019-09-19 15:36

MOT test number 899635308522

Result \rightarrow Passed

Advice

Result

Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))

MOT #2 2019-09-19 11:05

MOT test number 862666668965

00200000000

Fail Nearside Front Tyre fouling a part of the vehicle (5.2.3 (f))

MOT #1 2018-09-18 09:53

MOT test number 393392423785

Result
✓ Passed

CarCheck.co.uk page 4/11





Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



DN65BJE

report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



DN65BJE

report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

Plate changes	More info >
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NA
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-09-25
Last registration	2023-06-24
Complete history	See info



Registration #1	2015-09-25	8 mi
Registration #2	2018-09-18	30.858 mi
Registration #3	2019-09-19	42.697 mi
Registration #4	2019-09-19	42.697 mi
Registration #5	2020-09-15	51.053 mi
Registration #6	2020-09-15	51.055 mi
Registration #7		11.777 mi
Registration #8		71.777 es
Registration #9		11.777 mi
Registration #10		71.777 es
Registration #11		11.777 mi
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1434 mm
Length	4633 mm
Wheel base	2810 mm
Kerb weight	1630 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	57 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

Engine number 66959387