



report date: 2024-03-28

General information

Make	MAZDA
Model	3 TS
Colour	Silver
Year of manufacture	-
Top speed	113 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-07-08
Pictures	14
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-06-19
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #16	2022-01-24 11:57
MOT test number	417408055613
Result	✓ Passed
Next expiry date	2023-01-27
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15	2021-01-28 09:14
MOT test number	846152133124
Result	✓ Passed

MOT #14	2020-01-27 08:36
MOT test number	432009206633
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))

MOT #13	2019-01-28 12:29
MOT test number	645301732623
Result	✓ Passed

MOT #12	2018-01-08 11:41
MOT test number	761551289479
Result	✓ Passed
Advice	Nearside Rear tyre worn on inner edge
Advice	Nearside Front Tyre worn close to the legal limit on 1.6mm and worn on inner edge (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit on 1.6mm and worn on inner edge (4.1.E.1)

**MOT #11** 2018-01-08 09:50**MOT test number** 766129597930**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Nearside Front Tyre worn close to the legal limit on 1.6mm and worn on inner edge (4.1.E.1)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Rear tyre worn on inner edge**Advice** Offside Front Tyre worn close to the legal limit on 1.6mm and worn on inner edge (4.1.E.1)**MOT #10** 2017-01-16 09:15**MOT test number** 721892164046**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit inner tread (4.1.E.1)**Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush drop link (2.4.G.2)**MOT #9** 2016-01-07 12:20**MOT test number** 486136621605**Result** ✓ Passed**MOT #8** 2016-01-06 15:37**MOT test number** 625543301986**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #7** 2015-01-14 10:45**MOT test number** 366804615092**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Notice** Both front tyres wearing low/worn on inner edge
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6 2014-01-11 10:15**MOT test number** 299321614049**Result** ✓ Passed

- Notice** Nail in offside rear tyre

MOT #5 2014-01-11 10:15**MOT test number** 425701314094**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Notice** Nail in offside rear tyre
- Pass with rectification** Offside Headlamp aim too low (1.8)

MOT #4 2013-01-16 16:01**MOT test number** 175936813029**Result** ✓ Passed



MOT #3	2012-01-18 15:38
MOT test number	535138012066
Result	✓ Passed
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2	2011-05-26 09:47
MOT test number	917836541125
Result	✓ Passed

MOT #1	2010-05-18 14:25
MOT test number	542868830158
Result	✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-05-24
Last registration	2022-01-24
Complete history	See info



Registration #1	2007-05-24	9 mi
Registration #2	2010-05-18	27.608 mi
Registration #3	2011-05-26	35.744 mi
Registration #4	2012-01-18	38.448 mi
Registration #5	2013-01-16	48.154 mi
Registration #6	2014-01-11	57.439 mi
Registration #7	2015-01-14	66.137 mi
Registration #8	2016-01-06	73.601 mi
Registration #9	2016-01-07	73.601 mi
Registration #10	2016-01-07	73.601 mi
Registration #11	2016-01-07	73.601 mi
Registration #12	2016-01-07	73.601 mi
Registration #13	2016-01-07	73.601 mi
Registration #14	2016-01-07	73.601 mi
Registration #15	2016-01-07	73.601 mi
Registration #16	2016-01-07	73.601 mi
Registration #17	2016-01-07	73.601 mi
Registration #18	2016-01-07	73.601 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4420 mm
Wheel base	2640 mm
Kerb weight	1320 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z6 569538