



report date: 2024-03-29

General information

Make	CITROEN
Model	DISPATCH D 815 P/V
Colour	Blue
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	71 BHP
Max. torque	125 Nm at 2.500 rpm
Engine capacity	1.868 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-10
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-21
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	20
Total items failed	7

MOT #20 2023-12-22 16:46

MOT test number 486576291080

Result ✓ Passed

Next expiry date 2024-12-21

Advice Offside Front Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced (5.3.3 (b) (i))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Central Front Child Seat fitted not allowing full inspection of adult belt

MOT #19 2022-11-22 13:25

MOT test number 518249739578

Result ✓ Passed

MOT #18 2021-12-06 11:39

MOT test number 988010005052

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17** 2021-12-03 13:58**MOT test number** 881580201274**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #16** 2020-12-07 11:58**MOT test number** 385826546047**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2020-12-07 11:58**MOT test number** 433919905188**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Horn not working (7.7 (a) (ii))**MOT #14** 2019-05-15 11:36**MOT test number** 703595819658**Result** ✓ Passed**MOT #13** 2019-05-15 11:36**MOT test number** 637216708196**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))

**MOT #12** 2018-05-14 09:02**MOT test number** 411009927690**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #11** 2017-05-17 13:10**MOT test number** 529764528211**Result** ✓ Passed**MOT #10** 2016-05-18 11:38**MOT test number** 144544302894**Result** ✓ Passed**MOT #9** 2015-04-22 15:21**MOT test number** 256612615125**Result** ✓ Passed**Notice** Oil leak**MOT #8** 2015-04-22 15:21**MOT test number** 606782515129**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Oil leak**MOT #7** 2014-03-31 11:40**MOT test number** 767410294068**Result** ✓ Passed

**MOT #6** 2013-04-16 15:47**MOT test number** 338256103142**Result** ✓ Passed**MOT #5** 2012-03-09 09:20**MOT test number** 306749262098**Result** ✓ Passed**Notice** Standard fitment seat belt missing**Notice** Passenger seat(s) missing at time of test**MOT #4** 2011-03-11 16:36**MOT test number** 495490471089**Result** ✓ Passed**Notice** Service brake your vehicle has only just met the required service brake efficiency**Notice** Oil leak**MOT #3** 2011-03-11 10:58**MOT test number** 239370471088**Result** ✗ Failed**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Oil leak**Fail** Offside rear brake binding (3.7.B.1)**Notice** Harsh metallic sound emitting from offside rear brake**MOT #2** 2010-03-11 11:25**MOT test number** 603460170025**Result** ✓ Passed



MOT #1	2009-03-09 10:59
MOT test number	321708069057
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
21 December 2024

Tax status		Valid until 1 July
Days left		63
MOT expiry date		21 December 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-15
Last registration	2023-12-22
Complete history	See info



Registration #1	2006-03-15	27 mi
Registration #2	2009-03-09	30.301 mi
Registration #3	2010-03-11	36.972 mi
Registration #4	2011-03-11	43.920 mi
Registration #5	2011-03-11	43.920 mi
Registration #6	2012-03-09	50.501 mi
Registration #7	2013-04-16	58.021 mi
Registration #8	2014-03-31	63.044 mi
Registration #9	2015-04-22	67.419 mi
Registration #10	2016-05-18	67.423 mi
Registration #11	2017-05-17	67.628 mi
Registration #12	2018-05-22	67.628 mi
Registration #13	2019-05-22	67.628 mi
Registration #14	2020-05-22	67.628 mi
Registration #15	2021-05-22	67.628 mi
Registration #16	2022-05-22	67.628 mi
Registration #17	2023-05-22	67.628 mi
Registration #18	2024-05-22	67.628 mi
Registration #19	2025-05-22	67.628 mi
Registration #20	2026-05-22	67.628 mi
Registration #21	2027-05-22	67.628 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	2134 mm
Height	1940 mm
Length	4522 mm
Kerb weight	1390 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Indirect Injection
Number of doors	5
Number of seats	3
Engine number	DXFP6053124