



RK59ULO

report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X SPORT TDCI
Colour	Silver
Year of manufacture	-
Top speed	139 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	400 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg






Internet history

Entry 1

Date	2021-01-31
Pictures	4
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #15	2022-11-03 12:55
MOT test number	103634654880
Result	✓ Passed
Next expiry date	2023-11-16
Advice	Rear Exhaust mounting defective exhaust mount hanger corroded (6.1.2 (a))

MOT #14	2021-10-29 09:08
MOT test number	590393938418
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Central Exhaust mounting defective (6.1.2 (a))

MOT #13	2020-11-17 12:35
MOT test number	122414869117
Result	✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both pitted (1.1.14 (a) (ii))
Advice	Rear Coil spring corroded Both sides (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2020-11-17 12:35

MOT test number

283489418212

Result**✗ Failed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both pitted (1.1.14 (a) (ii))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

MOT #11

2019-09-25 07:55

MOT test number

689897354494

Result**✓ Passed**

- Advice** Vehicle undershields fitted obscuring some components
- Advice** Engine bay covers fitted obscuring some components

MOT #10

2018-08-08 10:50

MOT test number

430100613145

Result**✓ Passed****MOT #9**

2018-08-08 10:50

MOT test number

695820673530

Result**✗ Failed**

- Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #8** 2017-08-09 10:23**MOT test number** 902371988900**Result** ✓ Passed**Advice** Engine management light on**MOT #7** 2016-08-02 15:08**MOT test number** 524250763532**Result** ✓ Passed**MOT #6** 2015-08-03 10:07**MOT test number** 418445615253**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2015-08-03 10:07**MOT test number** 518975615270**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2014-08-16 12:09**MOT test number** 587598224291**Result** ✓ Passed

- Notice** Items removed from driver's view prior to test
- Notice** Engine managment light on
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #3 2014-08-12 11:12**MOT test number** 439024724283**Result** ✗ Failed

- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Items removed from driver's view prior to test
- Notice** Engine managment light on
- Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #2 2013-08-30 18:03**MOT test number** 366602843291**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2012-08-17 15:36
MOT test number	478510432224
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	RK59ULO
Plate since	2024-03-28
Current registration	RK59ULO
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-01
Last registration	2022-11-03
Complete history	See info



Registration #1	2009-09-01	16 mi
Registration #2	2012-08-17	61.947 mi
Registration #3	2013-08-30	77.427 mi
Registration #4	2014-08-12	83.571 mi
Registration #5	2014-08-16	83.644 mi
Registration #6	2015-08-03	89.044 mi
Registration #7	2016-08-02	95.001 mi
Registration #8	2017-08-09	101.325 mi
Registration #9	2018-08-09	107.649 mi
Registration #10	2019-08-09	113.973 mi
Registration #11	2020-08-09	120.297 mi
Registration #12	2021-08-09	126.621 mi
Registration #13	2022-08-09	132.945 mi
Registration #14	2023-08-09	139.269 mi
Registration #15	2024-08-09	145.593 mi
Registration #16	2025-08-09	151.917 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1570 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U48397