





report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO GBT
Colour	Black
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-02-03

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2025-03-10
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	12
Total items failed	7

MOT #13		2024-03-11 17:40
MOT test	number	320518361175
Result		✓ Passed
Next expi	ry date	2025-03-10
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2023-03-06 18:24
MOT test number	914449536126
Result	✓ Passed
Advice Offside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	

MOT #11		2022-03-08 13:01
MOT test	number	290506785415
Result		✓ Passed
Advice	Slight corrosion to rear exhaust box	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #10	2022-03-07 15:33
MOT test number	910639088125
Result	× Failed
Fail Offside Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Slight corrosion to rear exhaust box	
Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #9	2021-02-19 09:04
MOT test number	430713506874
Result	✓ Passed
MOT #8	2020-02-14 11:47
MOT test number	337198489376
Result	✓ Passed
MOT #7	2019-02-25 11:28
MOT test number	232275761269
Result	✓ Passed
MOT #6	2019-02-22 12:59
MOT test number	872355478098
Result	× Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5 2018-02-24 10:07

MOT test number 560704543916

MOT #4 2017-02-24 18:18

MOT test number 775227212047

Advice Nearside wiper blade split

MOT #3 2016-02-22 17:43

MOT test number 850351253512

Result ✓ Passed

MOT #2 2015-10-21 07:25

MOT test number 243015343159

Result
✓ Passed

MOT #1 2015-10-17 08:21

MOT test number 582291150151

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Centre Rear Stop lamp not working Intermitent (1.2.1b)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

EA62ENM

report date: 2024-03-29

Owner history		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report \underline{t}		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		

More info >

UK UK

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-10-20
Last registration	2024-03-11
Complete history	See info



Registration #1	2012-10-20	8 mi
Registration #2	2015-10-17	31.154 mi
Registration #3	2015-10-21	31.350 mi
Registration #4	2016-02-22	33.576 mi
Registration #5	2017-02-24	37.500 mi
Registration #6	2018-02-24	41.888 mi
Registration #7	2019-02-22	45.388 mi
Registration #8	2019-02-25	45.388 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.177 ms

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12