



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D3 SE LUX
Colour	Green
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.750 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-09-12
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

Entry 1

Date	2021-09-10
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-27
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	4
Total items failed	8

MOT #13	2023-07-28 12:34
MOT test number	370935424483
Result	✓ Passed
Next expiry date	2024-07-27

MOT #12	2022-06-28 09:10
MOT test number	680075718019
Result	✓ Passed
Advice	Offside Rear Nail in tyre

MOT #11	2021-11-03 11:10
MOT test number	668115329058
Result	✓ Passed

MOT #10	2021-09-24 11:31
MOT test number	820035201364
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9	2020-09-21 16:02
MOT test number	905138059916
Result	✓ Passed

**MOT #8** 2020-09-15 13:20**MOT test number** 711478990693**Result** ✗ Failed**Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #7** 2017-07-31 11:24**MOT test number** 786117660084**Result** ✓ Passed**MOT #6** 2017-07-31 09:21**MOT test number** 131148985495**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #5** 2016-07-12 11:47**MOT test number** 975276434982**Result** ✓ Passed**MOT #4** 2015-07-30 15:17**MOT test number** 545961215255**Result** ✓ Passed**Notice** Nsf/nsr tyre outerwalls damaged,no cords**Notice** Under-trays fitted obscuring some underside components



MOT #3	2014-04-09 13:50
MOT test number	356919294086
Result	✓ Passed
MOT #2	2013-06-28 08:32
MOT test number	455549373177
Result	✓ Passed
MOT #1	2013-06-28 08:32
MOT test number	405409373186
Result	✗ Failed
Pass with rectification	Nearside Front Side repeater not working (1.4.A.2c)
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
27 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	27 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-05-18
Last registration	2023-07-28
Complete history	<a href="#">See info</a>



Registration #1	2011-05-18	25 mi
Registration #2	2013-06-28	14.730 mi
Registration #3	2014-04-09	31.165 mi
Registration #4	2015-07-30	38.045 mi
Registration #5	2016-07-12	46.137 mi
Registration #6	2017-07-31	59.462 mi
Registration #7	2017-07-31	59.462 mi
Registration #8	2020-09-15	76.472 mi
Registration #9	2023-07-28	76.472 mi
Registration #10	2023-07-28	76.472 mi
Registration #11	2023-07-28	76.472 mi
Registration #12	2023-07-28	76.472 mi
Registration #13	2023-07-28	76.472 mi
Registration #14	2023-07-28	76.472 mi
Registration #15	2023-07-28	76.472 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1561 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	1026084
---------------	---------