





report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

### Entry 2

Date 2021-12-10

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-10-03
Pictures	14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-15
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	11
Total items failed	7

MOT #13	2023-11-16 12:22
MOT test number	498030340779
Result	✓ Passed
Next expiry date	2024-11-15

MOT #12	2023-03-20 12:01
MOT test number	990364332847
Result	✓ Passed

MOT #11	2022-02-05 13:38
MOT test number	969244451147
Result	<b>✓</b> Passed

MOT #10	2021-10-02 10:51
MOT test number	823929015652
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #9 2020-11-17 12:14

**MOT test number** 273690223910

**Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Rear Tyre worn close to legal limit/worn on edge low on inside edge (5.2.3 (e))

MOT #8 2019-11-21 14:47

MOT test number 966378760891

**Result** 
✓ Passed

MOT #7 2019-11-21 11:38

**MOT test number** 742171764146

Result X Failed

**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MAJOR** Rear Reversing lamp inoperative (4.6.1 (a))

**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #6 2018-11-30 15:59

**MOT test number** 543388204733

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

729255560364

Result

Pass with rectification (b) (ii))

Pass with rectification (b) (iii))

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (iii))

Pass with rectification (b) (iii))

Pass with rectification (b) (iii))

Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (iii))

**MOT #4** 2017-09-14 08:46 **MOT** test number 260776000086 Result Passed **MOT #3** 2017-09-12 12:12 **MOT** test number 803010453497 Result × Failed Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b) **Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g) Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b) Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b) **Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #2

MOT test number

Result

Advice Child Seat fitted not allowing full inspection of adult belt

Both Rear Tyre's Worn On Inner Edge

CarCheck.co.uk page 5/13



report date: 2024-03-29

**MOT #1** 2015-09-18 16:04

**MOT test number** 930518823230

CarCheck.co.uk page 6/13



report date: 2024-03-29

### Tax & MOT check



**MOT** 

Tax status	Valid until 1 November
Days left	186
MOT expiry date	15 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

## Owner history

•	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK SIE
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13




report date: 2024-03-29

## Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-01-10
Last registration	2023-11-16
Complete history	See info



Registration #1	2013-01-10	9 mi
Registration #2	2015-09-18	20.541 mi
Registration #3	2016-09-15	27.493 mi
Registration #4	2017-09-12	35.714 mi
Registration #5	2017-09-14	35.714 mi
Registration #6	2018-11-30	47.470 mi
Registration #7	2018-11-30	47.470 mi
Registration #8	2019-11-21	56.172 mi
Registration #9		11.177 es
Registration #10		71.777 es
Registration #11		11.177 mi
Registration #12		71.777 es
Registration #13		11.177 mi
Registration #14		11.117 es
Registration #15		11.177 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

## Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	227236K

CarCheck.co.uk page 13/13