



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN S TDI
Colour	White
Year of manufacture	2011
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 106 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	6.3 mpg
CO2 emission	134 g/km
CO2 label	E








Internet history

Entry 1

Date	2021-09-07
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-04
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #13	2023-07-28 14:06
MOT test number	876414783406
Result	✓ Passed
Next expiry date	2024-08-04
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12	2022-07-09 13:14
MOT test number	510926387119
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11	2021-08-05 14:33
MOT test number	167286182168
Result	✓ Passed

**MOT #10** 2021-08-05 10:47**MOT test number** 391764241593**Result** ✗ Failed**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #9** 2020-07-24 08:40**MOT test number** 868019485115**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #8** 2019-07-25 08:00**MOT test number** 485462357251**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2018-06-26 12:43**MOT test number** 451285386361**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-07-12 07:40**MOT test number** 110111255737**Result** ✓ Passed**Advice** Nearside Side repeater has light sources not illuminating, but not more than 50% (1.4.A.2c)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2017-07-11 12:59**MOT test number** 209621015156**Result** ✗ Failed

- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Advice** Nearside Side repeater has light sources not illuminating, but not more than 50% (1.4.A.2c)
- Fail** Nearside Rear coil spring fractured (2.4.C.1a)

MOT #4 2016-07-26 09:08**MOT test number** 947288567358**Result** ✓ Passed

- Advice** Nearside Rear tyre is bold on inner edge

MOT #3 2016-07-26 08:47**MOT test number** 628180973299**Result** ✗ Failed

- Advice** Both rear tyres are bold on inner edges
- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #2 2015-08-04 14:50**MOT test number** 796756015275**Result** ✓ Passed

- Notice** All 4 tyres starting to wear bold on inner edge



MOT #1	2014-08-21 15:36
MOT test number	786513334240
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
4 August 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 HY61UPW
Plate since	2024-03-29
Current registration	 HY61UPW
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-01
Last registration	2023-07-28
Complete history	See info



Registration #1	2011-09-01	24 mi
Registration #2	2014-08-21	30.465 mi
Registration #3	2015-08-04	46.202 mi
Registration #4	2016-07-26	58.029 mi
Registration #5	2016-07-26	58.029 mi
Registration #6	2017-07-11	65.240 mi
Registration #7	2017-07-12	65.240 mi
Registration #8	2018-06-26	70.713 mi
Registration #9	2019-06-26	75.207 mi
Registration #10	2020-06-26	75.207 mi
Registration #11	2021-06-26	75.207 mi
Registration #12	2022-06-26	75.207 mi
Registration #13	2023-06-26	75.207 mi
Registration #14	2024-03-29	75.207 mi
Registration #15	2024-03-29	75.207 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1634 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1539 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles

2

Engine number

CAY 586764