



report date: 2024-03-28

General information

Make	MINI
Model	MINI (R58) COOPER
Colour	Red
Year of manufacture	2007
Top speed	115 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	161 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-22
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-14
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	39
Total items failed	8

MOT #20	2023-08-15 08:56
---------	------------------

MOT test number	560872325888
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-14
------------------	------------

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Exhaust corroded
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Engine covers and undertrays fitted

**MOT #19** 2023-08-14 16:42**MOT test number** 214674536400**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust corroded**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Engine covers and undertrays fitted**MOT #18** 2022-08-11 12:29**MOT test number** 763404538956**Result** ✓ Passed**MOT #17** 2022-08-10 11:22**MOT test number** 474157105590**Result** ✗ Failed**MAJOR** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** N/s/r tyre starting to go out of shape**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MOT #16** 2021-10-20 14:17**MOT test number** 740196212855**Result** ✓ Passed

**MOT #15** 2021-10-15 09:44**MOT test number** 836050218270**Result** ✗ Failed

**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MAJOR** Emissions not tested because of coolant leak (8.2.1.2 (d))

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #14** 2020-12-11 11:21**MOT test number** 679064584137**Result** ✓ Passed**MOT #13** 2020-12-11 10:16**MOT test number** 860678752335**Result** ✗ Failed

**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12** 2019-11-05 11:54**MOT test number** 623390735200**Result** ✓ Passed**MOT #11** 2018-11-20 14:21**MOT test number** 113379533076**Result** ✓ Passed



<b>MOT #10</b>	2017-11-18 11:19
<b>MOT test number</b>	911321328376
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

<b>MOT #9</b>	2016-11-11 14:21
<b>MOT test number</b>	169248437695
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2016-10-17 12:47
<b>MOT test number</b>	298598356827
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm plus tread cracking (4.1.E.1)
<b>Fail</b>	Nearside Front Wheel bolt(s) missing (4.2.A.1e)
<b>Fail</b>	Offside Rear Registration plate lamp not working (1.1.C.1d)
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm plus tread cracking (4.1.E.1)
<b>Fail</b>	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits lambda reading to high was 1.567 (7.3.D.3)

<b>MOT #7</b>	2015-10-20 10:49
<b>MOT test number</b>	911092134880
<b>Result</b>	✓ Passed

<b>MOT #6</b>	2015-10-19 14:54
<b>MOT test number</b>	369327957904
<b>Result</b>	✗ Failed
<b>Fail</b>	Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
<b>Fail</b>	Front brake disc in such a condition that it is seriously weakened (3.5.1i)
<b>Fail</b>	Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #5** 2014-09-25 15:51**MOT test number** 995298664244**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** OSF tyre perishing**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)**Notice** Under-trays fitted obscuring some underside components**Notice** NSF tyre perishing**MOT #4** 2013-09-30 12:05**MOT test number** 546053473281**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**MOT #3** 2012-10-13 11:50**MOT test number** 899287082281**Result** ✓ Passed**MOT #2** 2011-10-24 13:58**MOT test number** 957317191205**Result** ✓ Passed



MOT #1	2010-06-28 10:35
MOT test number	244389070403
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
14 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	14 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	EY07KUU
Plate since	2019-03-28
Current registration	EY07KUU
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-07-17
Last registration	2023-08-15
Complete history	<a href="#">See info</a>



Registration #1	2007-07-17	6 mi
Registration #2	2010-06-28	14.913 mi
Registration #3	2011-10-24	19.949 mi
Registration #4	2012-10-13	24.691 mi
Registration #5	2013-09-30	29.050 mi
Registration #6	2014-09-25	32.010 mi
Registration #7	2015-10-19	36.664 mi
Registration #8	2015-10-20	36.664 mi
Registration #9	2016-10-17	40.883 mi
Registration #10	2016-11-11	40.889 mi
Registration #11	2017-11-18	42.389 mi
Registration #12	2018-05-20	45.277 mi
Registration #13	2018-05-20	45.277 mi
Registration #14	2018-05-20	45.277 mi
Registration #15	2018-05-20	45.277 mi
Registration #16	2018-05-20	45.277 mi
Registration #17	2018-05-20	45.277 mi
Registration #18	2018-05-20	45.277 mi
Registration #19	2018-05-20	45.277 mi
Registration #20	2018-05-20	45.277 mi
Registration #21	2018-05-20	45.277 mi
Registration #22	2018-05-20	45.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1180 kg
Max. allowed weight	1555 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	B330H943
---------------	----------