





report date: 2024-03-28

#### General information

Make	PEUGEOT
Model	207 SPORTIUM
Colour	Grey
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/14



## Internet history

#### Entry 1

Date 2021-12-16

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-07-27
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	39
Total items failed	15

MOT #16	2023-07-26 09:10
MOT test number	277882930547
Result	<b>✓</b> Passed
Next expiry date	2024-07-27
Advice Sill covers fitted	
Advice General underside surface corrosion	

MOT #15	2023-07-20 09:50
MOT test number	198105741233
Result	<b>X</b> Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice Sill covers fitted	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge edge we	ear (5.2.3 (e))
<b>Fail</b> Nearside Front Drive shaft joint constant velocity boot split or insecure, no ingress of dirt also check for wear (6.1.7 (g) (ii))	longer prevents the
Fail Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	
Advice General underside surface corrosion	
Advice Nearside Front Tyre worn close to legal limit/worn on edge max inner ed	dge wear (5.2.3 (e))
Fail Nearside Front Anti-roll bar ball joint excessively worn drop link (5.3.4 (a) (	i))

CarCheck.co.uk page 3/14



**MOT #14** 2022-07-27 16:52

**MOT test number** 903033542920

**Result** ✓ Passed

MOT #13 2022-07-21 11:39

**MOT test number** 931873428724

Result X Failed

**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #12** 2021-07-28 09:41

**MOT test number** 185963478519

Result \rightarrow Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11** 2021-07-26 09:58

MOT test number 420722707674

Result X Failed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #10** 2020-10-02 11:42

**MOT test number** 481000958511

Result 

Passed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Brake lever worn but not seriously weakened (1.1.15 (b))

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/14



MOT #9 2020-10-01 13:23

**MOT test number** 684444310811

**Result** X Failed

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Fail** Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen no screenwash (3.5 (a))

**Advice** Brake lever worn but not seriously weakened (1.1.15 (b))

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2019-04-23 08:51

MOT test number 153628253447

Result 

Passed

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Advice Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Rear Exhaust mounting defective (6.1.2 (a))

CarCheck.co.uk page 5/14



✓ Passed

MOT #7 2019-04-23 08:51

**MOT test number** 735146175157

Result × Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**Advice** Rear Exhaust mounting defective (6.1.2 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2018-04-23 08:44

**MOT test number** 263389917967

Advice Rear Lower Gearbox mounting defective bolt insecure throw mont

**Advice** Oil leak

Result

**Advice** Rear exhaust mont poor condition

**MOT #5** 2017-05-05 10:29

MOT test number 288406290445

**Result** 
✓ Passed

MOT #4 2017-05-02 16:18

**MOT test number** 607969877939

**Result** X Failed

Fail Central Stop lamp not working (1.2.1b)

CarCheck.co.uk page 6/14



MOT #3 2016-05-26 11:53

**MOT test number** 244117702662

**Result** ✓ Passed

**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)

Advice Rear exhaust mounting bracket missing but fully secure

**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)

MOT #2 2016-05-25 15:32

MOT test number 471189691648

**Result** X Failed

**Advice** Rear exhaust mounting bracket missing but fully secure

**Fail** Offside Rear wheel bearing rough when rotated (2.6.1)

**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)

**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)

MOT #1 2015-05-29 11:22

MOT test number 338619645195

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Under-trays fitted obscuring some underside components

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	27 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e mier meerty	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
********	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NIEZ ZIN UK
Plate since	
Current registration	RIV.
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-05-25
Last registration	2023-07-26
Complete history	See info



Registration #1	2012-05-25	23 mi
Registration #2	2015-05-29	25.824 mi
Registration #3	2016-05-25	29.717 mi
Registration #4	2016-05-26	29.717 mi
Registration #5	2017-05-02	32.440 mi
Registration #6	2017-05-05	32.440 mi
Registration #7	2018-04-23	44.139 mi
Registration #8	2019-04-23	54.761 mi
Registration #9	2019-04-23	54.761 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		91,700 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 es

More info >

CarCheck.co.uk page 13/14



## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1617 kg

## Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

**Engine number** FSX46410607