





report date: 2024-03-29

### General information

Make	FIAT
Model	BRAVO SPORT TJET
Colour	Blue
Year of manufacture	2007
Top speed	132 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 2.250 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	167 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



AMO7ENK report date: 2024-03-29

Internet history

C	-	٠	100		1
_		u		v	4

End y 1	
Date	2022-06-30
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

# MOT history

MOT expiry date	2024-09-26
MOT pass rate	100 %
MOT passed	14
Failed MOT tests	0
Total advice items	21
Total items failed	0

MOT #14		2023-09-11 09:04
MOT test	number	171829011684
Result		✓ Passed
Next expi	ry date	2024-09-26
Advice Front Tyre slightly damaged/cracking or perishing both tyres (5.2.3 (d) (ii))		
Advice	Front Registration plate deteriorated but not likely to be misread and rear (0.1 (b	))

MOT #13	2022-09-27 12:11
MOT test number	780477662869
Result	✓ Passed
MOT #12	2021-07-14 10:08
MOT test number	355460858835
Result	✓ Passed
Advice Exhaust system corroded	

MOT #11		2020-07-29 10:26
MOT test n	umber	850096886143
Result		✓ Passed
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple	lamps or light sources (4.7.1 (b)

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10

MOT test number

329697095079

Result

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing & 8 years old (5.2.3 (d) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing & 8 years old (5.2.3 (d) (ii))

MOT #9

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

MOT test number

Result

Advice Rear tyres perishing between tread.

Advice Nearside front tyre perishing outer sidewall.

2017-07-25 10:44

534297200172

✓ Passed

 MOT #7
 2016-07-11 10:12

 MOT test number
 308289673190

 Result
 ✓ Passed

MOT #6

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

2015-07-17 10:59

738988795183

✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Under-trays fitted obscuring some underside components

Notice Front brake discs corroding & wearing.

MOT #4

MOT test number

Result

Advice

Offside Upper Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT test number

248518492191

Result

Notice Rear exhaust silencer corroding.

Notice Front brake pads getting low.

Notice Centre exhaust offside mounting bracket missing, system still adequately supported.

Notice Front brake discs corroding & wearing.

 MOT #2
 2011-07-25 11:41

 MOT test number
 428506901227

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2010-07-23 12:30

**MOT test number** 213854000296

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-29

26 September 2024

### Tax & MOT check



Tax expired: 1 February 2024



Expires: 26 September 2024

Tax statusExpired at 1 February 2024Days left88 days too late

Full MOT history See MOT history

### Tax calculation

**MOT** expiry date

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



**AMO7ENK** 

report date: 2024-03-29

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SINE
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.5	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-07-27
Last registration	2023-09-11
Complete history	See info



Registration #1	2007-07-27	14 mi
Registration #2	2010-07-23	21.141 mi
Registration #3	2011-07-25	24.423 mi
Registration #4	2012-07-16	27.783 mi
Registration #5	2013-07-15	31.087 mi
Registration #6	2014-07-11	34.024 mi
Registration #7	2015-07-17	36.973 mi
Registration #8	2016-07-11	39.783 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1275 kg
Max. allowed weight	1785 kg

# Additional information

Fuel tank capacity	58 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page :	13/13

Number of axles 2
Engine number 1164652