




report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI BITURBO S/S
Colour	Silver
Year of manufacture	2018
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-20
Pictures	21
Listing price	View report



source: [heycar.co.uk](#)

Entry 1

Date	2021-07-07
Pictures	21
Listing price	View report



source: [heycar.co.uk](#)



MOT history

MOT expiry date	2025-04-18
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	13
Total items failed	0

MOT #6 2024-04-19 14:46

MOT test number 747503813280

Result ✓ Passed

Next expiry date 2025-04-18

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Outer Tyre slightly damaged/cracking or perishing outer tyre walls scuffed (5.2.3 (d) (ii))

MOT #5 2024-04-08 14:33

MOT test number 101737116537

Result ✗ Failed

MAJOR Rear Rear fog lamp not working No tell tale on dash, and fog light not working (4.5.1 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Outer Tyre slightly damaged/cracking or perishing outer tyre walls scuffed (5.2.3 (d) (ii))

MOT #4 2023-03-31 13:48

MOT test number 748816413060

Result ✓ Passed

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #3** 2023-03-28 14:41**MOT test number** 684775015926**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Rear fog lamp switch inoperative (4.5.3 (a))**MOT #2** 2022-04-04 14:42**MOT test number** 424858589410**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Outer Nail in tyre**Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Front Windscreen damaged but not adversely affecting driver's view crack in screen (3.2 (a) (i))**MOT #1** 2021-03-26 17:14**MOT test number** 511074889544**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
18 April 2025

Tax status		Valid until 1 September
Days left		126
MOT expiry date		18 April 2025
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	CU18ZBP
Plate since	2019-03-28
Current registration	CU18ZBP
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-26
Last registration	2024-04-19
Complete history	See info



Registration #1	2018-03-26	13 mi
Registration #2	2021-03-26	48.510 mi
Registration #3		
Registration #4		
Registration #5	2022-04-04	62.714 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1760 kg
Max. allowed weight	3040 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M D4 - C332000LQI