



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SPORT
Colour	White
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-04
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #15	2022-08-10 13:58
MOT test number	896594903513
Result	✓ Passed
Next expiry date	2023-08-09

MOT #14	2021-08-10 12:43
MOT test number	668991437515
Result	✓ Passed

MOT #13	2020-10-12 15:42
MOT test number	962167271856
Result	✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Both rears worn (1.1.14 (a) (ii))
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge On 3mm and cuts in sidewall (5.2.3 (e))

MOT #12	2019-04-17 08:54
MOT test number	588922478164
Result	✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt

MOT #11	2018-04-16 10:46
MOT test number	530639506025
Result	✓ Passed

**MOT #10** 2017-04-18 09:42**MOT test number** 912868700252**Result** ✓ Passed**MOT #9** 2016-08-31 10:43**MOT test number** 424362943975**Result** ✓ Passed**MOT #8** 2016-08-30 12:51**MOT test number** 720278500049**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2015-08-25 13:28**MOT test number** 446074357655**Result** ✓ Passed**MOT #6** 2015-08-25 08:45**MOT test number** 809912265114**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2014-08-14 11:42**MOT test number** 887056224293**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2014-08-14 07:59**MOT test number** 855656824296**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2013-08-29 15:36**MOT test number** 389741043454**Result** ✓ Passed**MOT #2** 2012-09-01 10:19**MOT test number** 349215442404**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Notice** Service light on dash**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2012-08-31 14:32**MOT test number** 867464942260**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Notice** Service light on dash**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-20
Last registration	2022-08-10
Complete history	See info



Registration #1	2009-06-20	20 mi
Registration #2	2012-08-31	28.675 mi
Registration #3	2012-09-01	28.682 mi
Registration #4	2013-08-29	36.386 mi
Registration #5	2014-08-14	43.680 mi
Registration #6	2014-08-14	43.680 mi
Registration #7	2015-08-25	51.390 mi
Registration #8	2015-08-25	51.393 mi
Registration #9	2016-08-30	58.678 mi
Registration #10	2016-08-30	58.678 mi
Registration #11	2016-08-30	58.678 mi
Registration #12	2016-08-30	58.678 mi
Registration #13	2016-08-30	58.678 mi
Registration #14	2016-08-30	58.678 mi
Registration #15	2016-08-30	58.678 mi
Registration #16	2016-08-30	58.678 mi
Registration #17	2016-08-30	58.678 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Engine number

156670