




report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	White
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-10-25
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	23
Total items failed	7

MOT #13	2023-10-25 12:55
MOT test number	832169306387
Result	✓ Passed
Next expiry date	2024-10-25

MOT #12	2022-10-26 10:18
MOT test number	742285942641
Result	✓ Passed

MOT #11	2022-10-26 10:18
MOT test number	473314380436
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))

**MOT #10** 2021-10-07 12:08**MOT test number** 423257599956**Result** ✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Steering wheel has slight play
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Coolant level low

MOT #9 2020-10-18 14:49**MOT test number** 740366824459**Result** ✓ Passed**MOT #8** 2019-12-20 13:49**MOT test number** 330033538464**Result** ✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))

**MOT #7** 2019-12-20 13:49**MOT test number** 798657957405**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))**MOT #6** 2019-01-30 11:32**MOT test number** 563650399318**Result** ✓ Passed**MOT #5** 2018-01-30 15:16**MOT test number** 543163143813**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Oil leak**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2018-01-18 13:30**MOT test number** 785885179648**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Brake performance not tested rear brakes metal to metal (3.7.A.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Oil leak
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2017-01-20 12:04**MOT test number** 483642872318**Result** ✓ Passed**MOT #2** 2016-04-19 11:53**MOT test number** 160467395982**Result** ✓ Passed**MOT #1** 2015-09-23 13:51**MOT test number** 310696547337**Result** ✓ Passed

- Advice** Oil leak from engine



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-12-15
Last registration	2023-10-25
Complete history	See info



Registration #1	2012-12-15	26 mi
Registration #2	2015-09-23	10.823 mi
Registration #3	2016-04-19	11.774 mi
Registration #4	2017-01-20	21.745 mi
Registration #5	2018-01-18	33.854 mi
Registration #6	2018-01-30	34.111 mi
Registration #7	2019-01-30	45.673 mi
Registration #8	2019-12-20	52.652 mi
Registration #9	2020-01-20	52.652 mi
Registration #10	2020-01-20	52.652 mi
Registration #11	2020-01-20	52.652 mi
Registration #12	2020-01-20	52.652 mi
Registration #13	2020-01-20	52.652 mi
Registration #14	2020-01-20	52.652 mi
Registration #15	2020-01-20	52.652 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	202373K