



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	108 ACTIVE
Colour	Silver
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	95 Nm at 4.300 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	56.5 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A





## Internet history

### Entry 4


Date	2021-10-11
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

### Entry 3

Date	2021-09-14
Pictures	43
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 2

Date	2021-09-14
Pictures	0
Listing price	<a href="#">View report</a>

source: [heycar.co.uk](https://www.heycar.co.uk)

### Entry 1

Date	2021-09-12
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-09-27
<b>MOT pass rate</b>	80 %
<b>MOT passed</b>	4
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	7
<b>Total items failed</b>	1

<b>MOT #5</b>	2023-09-06 09:58
<b>MOT test number</b>	822451539238
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-09-27
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #4</b>	2022-09-16 14:12
<b>MOT test number</b>	160943888526
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2022-09-16 14:12
<b>MOT test number</b>	720710806595
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #2	2021-09-01 10:24
MOT test number	745884461043
Result	✓ Passed
Advice	Offside Rear Nail in tyre also perishing on tread
Advice	Offside Front Tyre worn close to legal limit/worn on edge also perishing on tread (5.2.3 (e))
Advice	Nearside Rear tyre perishing on tread
Advice	Nearside Front Tyre worn close to legal limit/worn on edge also perishing on tread (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened corroded on face (1.1.14 (a) (ii))

MOT #1	2020-09-19 09:19
MOT test number	155025380706
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
27 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	27 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>First licence fee (12 months)</b>	£ 165,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-28
Last registration	2023-09-06
Complete history	<a href="#">See info</a>



Registration #1	2017-09-28	15 mi
Registration #2	2020-09-19	16.140 mi
Registration #3	2021-09-01	23.148 mi
Registration #4	2022-09-01	25.277 mi
Registration #5	2023-09-06	26.277 mi
Registration #6	2024-03-28	26.277 mi
Registration #7	2024-03-28	26.277 mi
Registration #8	2024-03-28	26.277 mi
Registration #9	2024-03-28	26.277 mi
Registration #10	2024-03-28	26.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3475 mm
Wheel base	2340 mm
Kerb weight	840 kg
Max. allowed weight	1240 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	8383230