



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS D-4D T SPIRIT
Colour	Grey
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	310 Nm at 2.400 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-07-12
Pictures	9
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-11
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	29
Total items failed	5

MOT #10	2023-08-24 09:00
MOT test number	111055756982
Result	✓ Passed
Next expiry date	2024-09-02
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Rear axle slightly corroded
Advice	Offside Rear Nail in tyre
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9** 2022-09-03 11:26**MOT test number** 299960187896**Result** ✓ Passed

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Tyre slightly damaged/cracking or perishing all four (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #8 2021-04-23 14:02**MOT test number** 213005921931**Result** ✓ Passed**MOT #7** 2021-04-23 12:33**MOT test number** 579042871412**Result** ✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

**MOT #6** 2019-04-13 08:52**MOT test number** 246660301419**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 215/55/17 (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #5 2019-04-13 08:52**MOT test number** 276109713776**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 215/55/17 (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2018-04-25 09:34**MOT test number** 656320039992**Result** ✓ Passed

- Advice** Offside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #3** 2017-09-08 19:54**MOT test number** 575060310735**Result** ✓ Passed**Advice** Can not check all items due to locations and covers etc**MOT #2** 2015-11-26 16:29**MOT test number** 689185168833**Result** ✓ Passed**MOT #1** 2015-11-26 15:25**MOT test number** 402380925663**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Headlamp aim too low (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
2 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	2 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-11
Last registration	2023-08-24
Complete history	See info



Registration #1	2012-09-11	29 mi
Registration #2	2015-11-26	46.654 mi
Registration #3	2015-11-26	46.654 mi
Registration #4	2017-09-08	74.660 mi
Registration #5	2018-04-25	80.128 mi
Registration #6	2019-04-13	98.816 mi
Registration #7	2019-04-13	98.816 mi
Registration #8	2019-04-13	98.816 mi
Registration #9	2019-04-13	98.816 mi
Registration #10	2019-04-13	98.816 mi
Registration #11	2019-04-13	98.816 mi
Registration #12	2019-04-13	98.816 mi
Registration #13	2019-04-13	98.816 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4780 mm
Wheel base	2700 mm
Kerb weight	1635 kg
Max. allowed weight	2130 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

1AD5645340