





report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Red
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 4

Date 2021-08-06

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

2021-07-23

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-07-09

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk



✓ Passed

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

Result

MOT expiry date	2024-06-30
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	21
Total items failed	0

MOT #11	2023-06-01 16:09
MOT test number	974643793671
Result	✓ Passed
Next expiry date	2024-06-30
Advice Nearside Play in steering rack inner joint(s)	

 MOT #10
 2023-06-01 11:05

 MOT test number
 191241696797

Result X Failed

MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Play in steering rack inner joint(s)

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

 MOT #9
 2022-07-01 10:09

 MOT test number
 565926434529

CarCheck.co.uk page 3/12



MOT #8 2022-06-28 15:33

MOT test number 841425983662

Result X Failed

DANGEROUS Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #7 2021-01-05 15:21

MOT test number 516341599799

Result ✓ Passed

MOT #6 2020-03-17 10:37

MOT test number 592764483897

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #5 2019-03-20 10:12

MOT test number 107792735452

Advice Offside Rear Lower Exhaust bracket slight corrosion

CarCheck.co.uk page 4/12



MOT #4 2019-03-19 10:14

MOT test number 642437247353

Result X Failed

MAJOR Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush slight cracking (5.3.4 (a) (i))

MAJOR Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush slight cracking (5.3.4 (a) (i))

Advice Offside Rear Lower Exhaust bracket slight corrosion

MOT #3 2018-03-12 10:52

MOT test number 939113693369

Result \rightarrow Passed

MOT #2 2017-03-30 13:55

MOT test number 415649171138

Result

Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2016-03-29 08:36

MOT test number 520872069315

Result
✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
THE STREET STREE	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-03-30
Last registration	2023-06-01
Complete history	See info



Registration #1	2013-03-30	26 mi
Registration #2	2016-03-29	38.017 mi
Registration #3	2017-03-30	51.843 mi
Registration #4	2018-03-12	63.040 mi
Registration #5	2019-03-19	72.694 mi
Registration #6	2019-03-20	72.694 mi
Registration #7	2020-03-17	82.386 mi
Registration #8	2021-01-05	88.263 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		0.00 44
Registration #15		10.777 au
_		

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12