



report date: 2024-03-29

General information

Make	KIA
Model	SEDONA SE
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	16.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	143 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	32.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-14
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #26

2024-02-15 11:12

MOT test number

942347578225

Result

✗ Failed

Advice Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

Fail Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

Advice Central Front Gearbox mounting defective loose bolts

Fail Nearside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

Fail Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Fail Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

Minor Nearside Rear Brake pipe inadequately clipped or supported (1.1.11 (d) (i))

Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Offside Rear Suspension arm corroded and seriously weakened (5.3.3 (b) (i))

MOT #25

2023-02-23 09:32

MOT test number

354836217876

Result

✓ Passed

MOT #24

2023-02-03 13:24

MOT test number

232949335626

Result

✗ Failed

Fail Brake hydraulic reservoir fluid level significantly below minimum level (1.1.10 (d) (ii))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Fail Central Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))

Fail Emissions not tested heavy black smoke (8.2.2.2 (e))

**MOT #23** 2022-01-26 11:05**MOT test number** 493201230152**Result** ✓ Passed**MOT #22** 2022-01-21 15:15**MOT test number** 170533543863**Result** ✗ Failed

- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #21 2021-01-06 12:01**MOT test number** 881033154087**Result** ✓ Passed**MOT #20** 2021-01-06 12:01**MOT test number** 842812579107**Result** ✗ Failed

- Pass with rectification** Central Windscreen washer provides insufficient washer liquid (3.5 (a))
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #19 2020-01-15 08:12**MOT test number** 842832172959**Result** ✓ Passed

- Advice** Nearside Rear Inner Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

**MOT #18** 2020-01-15 08:12**MOT test number** 821676498627**Result** ✗ Failed

Advice Nearside Rear Inner Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #17 2019-01-05 15:42**MOT test number** 933749619210**Result** ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Inner Vehicle structure is fractured but structural rigidity is not significantly reduced (6.1.1 (a) (i))

Advice Nearside Rear Inner Vehicle structure is fractured but structural rigidity is not significantly reduced (6.1.1 (a) (i))

MOT #16 2018-01-04 15:10**MOT test number** 531291957103**Result** ✓ Passed**MOT #15** 2017-01-04 12:35**MOT test number** 967593518906**Result** ✓ Passed

Advice Nearside mirror damaged

**MOT #14**

2017-01-03 10:11

MOT test number

266987924038

Result

✗ Failed

Fail Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Nearside Seat belt anchorage prescribed area is excessively corroded centre sill (5.2.6)

Fail Offside rear parking brake recording little or no effort very low (3.7.B.6a)

Fail Offside Rear Brake pipe excessively corroded on axle (3.6.B.2c)

Advice Nearside mirror damaged

Fail Nearside Rear Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #13

2016-01-07 09:44

MOT test number

326390937295

Result

✓ Passed

Advice 2 child seats fitted in rear seats

MOT #12

2015-01-08 14:58

MOT test number

257398105059

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2015-01-06 10:23

MOT test number

906656805016

Result**✗ Failed**

- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Front Headlamp aim too high (1.8)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Centre Power steering pipe(s) or hose(s) leaking (2.3.3b)

MOT #10

2014-01-09 09:30

MOT test number

489709304088

Result**✓ Passed****MOT #9**

2013-01-07 09:41

MOT test number

947247303025

Result**✓ Passed**

- Notice** Both front tyres thin on edge

MOT #8

2012-01-10 10:16

MOT test number

777920512080

Result**✓ Passed**



MOT #7 2011-01-11 17:33

MOT test number 265821911065

Result ✓ Passed

MOT #6 2011-01-06 09:08

MOT test number 625816101022

Result ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)

MOT #5 2010-01-07 17:01

MOT test number 643207400080

Result ✓ Passed

MOT #4 2009-02-27 16:09

MOT test number 690708359001

Result ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Oil leak
- Notice** Front bot hsteering rack arms play



MOT #3	2009-02-26 10:42
MOT test number	191977559005
Result	✗ Failed
Notice	Front bot hsteering rack arms play
Fail	Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
Fail	Rear All position lamps not working (1.1.A.3b)
Notice	Oil leak
Fail	Rear Exhaust system not adequately supported (7.1.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Front All position lamps not working (1.1.A.3b)
Fail	Rear Registration plate lamp not working (1.1.5c)

MOT #2	2008-01-09 10:55
MOT test number	462649508033
Result	✓ Passed
Advice	Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #1	2007-01-02 14:13
MOT test number	474252107037
Result	✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YE53VDG
Plate since	2019-03-29
Current registration	YE53VDG
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2004-01-23
Last registration	2024-02-15
Complete history	See info



Registration #1	2004-01-23	29 mi
Registration #2	2007-01-02	34.050 mi
Registration #3	2008-01-09	42.216 mi
Registration #4	2009-02-26	49.530 mi
Registration #5	2009-02-27	49.530 mi
Registration #6	2010-01-07	54.152 mi
Registration #7	2011-01-06	59.030 mi
Registration #8	2011-01-11	59.030 mi
Registration #9	2012-01-10	64.435 mi
Registration #10	2013-01-07	67.794 mi
Registration #11	2014-01-09	71.485 mi
Registration #12	2015-01-06	75.871 mi
Registration #13	2015-01-08	75.873 mi
Registration #14	2016-01-07	79.460 mi
Registration #15	2016-01-07	83.047 mi
Registration #16	2016-01-07	86.634 mi
Registration #17	2016-01-07	90.221 mi
Registration #18	2016-01-07	93.808 mi
Registration #19	2016-01-07	97.395 mi
Registration #20	2016-01-07	100.982 mi
Registration #21	2016-01-07	104.569 mi
Registration #22	2016-01-07	108.156 mi
Registration #23	2016-01-07	111.743 mi
Registration #24	2016-01-07	115.330 mi
Registration #25	2016-01-07	118.917 mi
Registration #26	2016-01-07	122.504 mi

Registration #27	2023-25-27	25,277-462
Registration #28	2023-25-28	25,277-462

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2184 mm
Height	1735 mm
Length	4890 mm
Wheel base	2905 mm
Kerb weight	2088 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	J3000 646628