



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 LWB CDV 104TDI PD
Colour	Black
Year of manufacture	2009
Top speed	102 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-02-07
MOT pass rate	100 %
MOT passed	12
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #12	2024-02-08 16:34
MOT test number	616711394974
Result	✓ Passed
Next expiry date	2025-02-07

MOT #11	2022-10-06 14:14
MOT test number	441823641885
Result	✓ Passed

MOT #10	2021-08-23 08:02
MOT test number	382148662220
Result	✓ Passed

Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

MOT #9	2020-09-23 14:08
MOT test number	115682987616
Result	✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))

**MOT #8** 2019-09-19 10:39**MOT test number** 349201219353**Result** ✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear Bush (5.3.4 (a) (i))

MOT #7 2018-09-20 09:58**MOT test number** 270771438717**Result** ✓ Passed**MOT #6** 2017-09-19 10:35**MOT test number** 973290394813**Result** ✓ Passed**MOT #5** 2016-09-15 11:02**MOT test number** 463824238204**Result** ✓ Passed

Advice Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)

Advice Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)

Advice Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #4 2015-09-17 08:23**MOT test number** 300126349271**Result** ✓ Passed

Advice Offside Front Suspension arm has slight play in a pin/bush Rear bush (2.4.G.2)

Advice Nearside Front Suspension arm has slight play in a pin/bush Rear bush (2.4.G.2)



MOT #3	2014-09-08 16:23
MOT test number	379941254233
Result	✓ Passed

MOT #2	2013-08-29 14:48
MOT test number	808531343283
Result	✓ Passed

MOT #1	2012-08-24 09:13
MOT test number	137937432205
Result	✓ Passed

Notice Towbar wiring not working as it should



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 February 2025

Tax status	Valid until 1 September
-------------------	-------------------------

Days left 124

MOT expiry date	7 February 2025
------------------------	-----------------

Full MOT history [See MOT history](#)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VO59OKL
Plate since	2019-06-29
Current registration	 VO59OKL
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-09-14
Last registration	2024-02-08
Complete history	See info



Registration #1	2009-09-14	27 mi
Registration #2	2012-08-24	55.044 mi
Registration #3	2013-08-29	73.636 mi
Registration #4	2014-09-08	87.951 mi
Registration #5	2015-09-17	97.568 mi
Registration #6	2016-09-15	107.935 mi
Registration #7	2017-09-19	123.341 mi
Registration #8	2018-09-20	133.777 mi
Registration #9	2019-09-20	144.213 mi
Registration #10	2020-09-20	154.649 mi
Registration #11	2021-09-20	165.085 mi
Registration #12	2022-09-20	175.521 mi
Registration #13	2024-02-08	185.957 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Length	4875 mm

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	BLS 579359