



AD59VWW

report date: 2024-03-29

General information

Make	FORD
Model	C-MAX TITANIUM TDCI
Colour	Blue
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-25
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-21
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	39
Total items failed	6

MOT #18	2024-02-10 14:22
MOT test number	345966354960
Result	✓ Passed
Next expiry date	2025-02-21
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17	2024-02-10 09:58
MOT test number	474288880605
Result	✗ Failed
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
MAJOR	Nearside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Rear Rear fog lamp not working (4.5.1 (a) (ii))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16** 2023-02-22 12:24**MOT test number** 681784140984**Result** ✓ Passed**MOT #15** 2022-01-07 10:03**MOT test number** 285382931476**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Exhaust mount corroded**MOT #14** 2021-01-08 17:35**MOT test number** 771667484435**Result** ✓ Passed**MOT #13** 2021-01-08 12:23**MOT test number** 526363182255**Result** ✗ Failed**MAJOR** Rear Registration plate inscription illegible (0.1 (b))**MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #12**

2020-01-02 17:35

MOT test number

655394057725

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge also has a nail (5.2.3 (e))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2020-01-02 14:36

MOT test number

908321789759

Result

✗ Failed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge also has a nail (5.2.3 (e))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2018-12-31 13:55

MOT test number

211617429308

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #9

2018-12-31 13:55

MOT test number

300854229164

Result

✗ Failed

- Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #8** 2017-12-22 11:37**MOT test number** 935599991168**Result** ✓ Passed

- Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #7 2016-12-05 12:44**MOT test number** 792291271123**Result** ✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Tyre worn close to the legal limit worn inner edge (4.1.E.1)

MOT #6 2015-11-23 15:30**MOT test number** 482894342709**Result** ✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #5 2015-11-23 11:08**MOT test number** 804670865284**Result** ✗ Failed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

**MOT #4** 2014-11-25 15:08**MOT test number** 359829724377**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #3** 2013-11-19 14:08**MOT test number** 698193823368**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2013-11-18 09:25**MOT test number** 238062223347**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2012-12-05 16:06**MOT test number** 486180742390**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
21 February 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-01-22
Last registration	2024-02-10
Complete history	See info



Registration #1	2010-01-22	16 mi
Registration #2	2012-12-05	8.315 mi
Registration #3	2013-11-18	25.608 mi
Registration #4	2013-11-19	25.618 mi
Registration #5	2014-11-25	43.557 mi
Registration #6	2015-11-23	63.593 mi
Registration #7	2015-11-23	63.595 mi
Registration #8	2016-12-05	81.203 mi
Registration #9	2017-12-22	87.268 mi
Registration #10	2018-12-31	90.835 mi
Registration #11	2019-01-01	90.835 mi
Registration #12	2019-01-01	90.835 mi
Registration #13	2019-01-01	90.835 mi
Registration #14	2019-01-01	90.835 mi
Registration #15	2019-01-01	90.835 mi
Registration #16	2019-01-01	90.835 mi
Registration #17	2019-01-01	90.835 mi
Registration #18	2019-01-01	90.835 mi
Registration #19	2019-01-01	90.835 mi
Registration #20	2019-01-01	90.835 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number

AU21080