





General information

| Make | FIAT |
|---------------------|-----------------------|
| Model | DOBLO 16V SX MULTIJET |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 102 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 105 BHP | 0 < 101 A |
|-------------------------|---------------------|---------------|
| Max. torque | 290 Nm at 1.500 rpm | 101 - 120 B |
| Engine capacity | 1.598 cc | 121 - 140 E |
| Cylinders | 4 | 141 - 165 F G |
| Fuel type | Diesel | 166 - 185 |
| Consumption city | 42.2 mpg | 186 - 225 J |
| Consumption extra urban | 60.1 mpg | 225+ L |
| Consumption combined | 52.3 mpg | |





Internet history


| Er | ntry | 1 |
|----|------|---|
| | | |

Date Pictures 2022-03-04

21

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-02-21 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 11 |
| Failed MOT tests | 0 |
| Total advice items | 8 |
| Total items failed | 0 |

| MOT #11 | 2024-02-17 10:08 |
|--|------------------|
| MOT test number | 423539212087 |
| Result | ✓ Passed |
| Next expiry date 2025-02-2 | |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened Inner face. (1.1.14 (a) (ii)) | |

| MOT #10 | 2023-02-20 16:23 |
|--|--|
| MOT test | number 670777076014 |
| Result | ✓ Passed |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |

| MOT #9 | 2022-02-22 11:43 |
|--|------------------|
| MOT test number | 901935584642 |
| Result | ✓ Passed |
| Advice No. plates, starting to delaminate - both | |

| MOT #8 | 2 | 2021-03-26 15:49 |
|----------|---|------------------|
| MOT test | number | 401370117332 |
| Result | | 🗸 Passed |
| Advice | Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (| a) (ii)) |





| MOT #7 | 2020-03-17 15:15 | |
|---|------------------|--|
| MOT test number | 604126550575 | |
| Result | ✓ Passed | |
| Advice Rear Lower Shock absorbers has a slightly worn bush Both (5.3.2 (c)) | | |
| MOT #6 | 2019-04-01 12:35 | |
| MOT test number | 317783074941 | |
| Result | 🗸 Passed | |
| Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c)) | | |
| MOT #5 | 2018-03-23 14:58 | |
| MOT test number | 439809772476 | |
| Result | ✓ Passed | |
| Advice Parking brake lever has little reserve travel (3.1.6b) | | |

| MOT #4 | 2017-03-16 10:57 |
|-----------------|------------------|
| MOT test number | 954731082030 |
| Result | ✓ Passed |
| | |

| MOT #3 | 2016-03-18 14:41 |
|-----------------|------------------|
| MOT test number | 799715225153 |
| Result | ✓ Passed |

| MOT #2 | 2015-03-20 12:35 |
|-----------------|------------------|
| MOT test number | 276699275025 |
| Result | ✓ Passed |

| MOT #1 | 2014-03-26 14:28 |
|-----------------|------------------|
| MOT test number | 749595584013 |
| Result | ✓ Passed |



Tax & MOT check







Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | FEIDO |
| Category | 4. ALANPE |
| Туре | |
| Damage 2 | AMPL |
| | F Store |
| Date | 1. E |
| Category | ame |
| Туре | |

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and a second s | |
|---|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 13 |
| First mileage registration | 2011-03-24 |
| Last registration | 2024-02-17 |
| Complete history | <u>See info</u> |



| Registration #1 | 2011-03-24 | 19 mi |
|------------------|------------|------------|
| Registration #2 | 2014-03-26 | 31.343 mi |
| Registration #3 | 2015-03-20 | 37.966 mi |
| Registration #4 | 2016-03-18 | 48.401 mi |
| Registration #5 | 2017-03-16 | 56.692 mi |
| Registration #6 | 2018-03-23 | 66.596 mi |
| Registration #7 | 2019-04-01 | 74.571 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 esi |
| Registration #13 | | 10.200 est |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|------------------------|------------------|
| Width | 1789 mm |
| Height | 1845 mm |
| Length | 4390 mm |
| Kerb weight | 1445 kg |
| Additional information | |
| Fuel tank capacity | 60 I |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 2 |
| Engine number | 6684130 |